

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 4937R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SAFE STOP TMA TRUCK MOUNTED ATTENUATORS	BUCKLED	70,000.00	17,000.00
			70,000.00	17,000.00
	<u>LABOUR</u>			
	SUPPLY OF METAL BRACKET FOR THE TMA INSTALLATION.	NOT NECESSARY	1,500.00	-
	FLASHNG ARROW LED LIGHT BOARD FOR BOTH SIDE.	NOT NECESSARY	1,200.00	-
	XENON STROBE LIGHT ON TOP.	NOT NECESSARY	600.00	-
	DANGER KEEP CLEAR - YELLOW GREEN TYPE WITH SIGN PANEL.		800.00	200.00
	YELLOW GREEN TYPE WIDE ANGEL PRISMATIC STICKER "SPLIT CHEVRON".		900.00	300.00
	YELLOW GREEN TYPE WIDE ANGLE PRISMATIC STICKER WITH TRUCK NUMBER.	NOT NECESSARY	600.00	-
	CUSTOMIZED TMA ID PLATE.	NOT NECESSARY	400.00	-
	TO DISMANTLE AND INSTALL NEW TMA, FOCUS ON DAMAGED PORTIN, PANEL BEATING ON RESHAPER, STRAIGHTEN, ORIENTATE AND ALIGN THE WHOLE REPAIR.		5,000.00	1,200.00
	TO DO THE ALIGNMENT, AFTER THE TMA INSTALLATION.	NOT NECESSARY	300.00	-
	TO DO ALL THE LED WORING LIGHT SETTING UP WORK AND CHECK WIRING.		1,000.00	60.00
	TO INSTALL THE YELLOW GREEN TYPE SIGN PANEL.	NOT NECESSARY	500.00	-
	REMOVE EXISTING TMA, REMOVE THE OLD TYPE OF FRAME AND OLD TYPE TMA SUPPORT.	NOT NECESSARY	2,000.00	-
	REMOVE AND INSTALL ALL NEW SET OF STICKER.		800.00	400.00
	INSTALL TMA ID PLATE.	NOT NECESSARY	300.00	-
	SUPPLY SPRAY MATERIAL TO TMA AND REAR DAMAGED PORTION.	NOT NECESSARY	3,000.00	-
			18,900.00	2,160.00
	GRAND TOTAL		88,900.00	19,160.00

Report Ref No. CS/FCI22000740/Rqf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)		19,160.00
LESS EXCESS		-2,500.00
NETT LIABILITY		16,660.00

Report Ref No. CS/FCI22000740/Rqf3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser