4/13/22, 10:33 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB22000743/UEA3Q2

**Date:** 13/04/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

Claimant Vehicle FBL9173M Insured Vehicle No: SLS5170S

No: Insured venicle No: 5L551705

Date of Loss: 08/01/2022 Nature of Claim: TP Claim No: MFL2022D0000235

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBL9173M

 Make & Model:
 HONDA CB190X, 184cc
 Engine No:
 SDH161FMKH3200514

 Reg. Date:
 17/05/2017 (Man. Year: 2017)
 Chassis No:
 LALPJL700H3018031

Colour: Red Odometer: 68910 km

Engine Capacity: 184 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 110-70 R17 Rear Tyre Size: 140-70 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,822.30	2,998.00	824.30	21.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	320.00	220.00	100.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,142.30	3,218.00	924.30	22.31
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	4,142.30	2,500.00	1,642.30	39.65
+ Loss of Use (3.0 x S\$	20.00/day) (S\$)	60.00		
Ne	ett Liability (S\$)	2,560.00		

INSPECTION

Date of Assignment: 20/01/2022

F.T. Fasttrack (HQ)

Date Inspected: 20/01/2022 Inspected At: 25 Kaki Bukit Road 4, #01-77

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

**Part Source:** (Last Synchronised: 21 Mar 2022)

Parts: N/A HONDA CB190X 184cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBL9173M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	155.00 FL	*155.00 FL
2	1		*SET HANDLE GUARD	Cut	180.00 FL	*180.00 FL
3	1		*BALANCER (RH)	Cut	35.00 FL	*35.00 FL
4	1		*MIRROR (RH)	Cut	90.00 FL	*90.00 FL
5	1		*FRONT & REAR SIGNAL LAMP (RH)	Frt Cut	194.00 FL	*97.00 FL
6	1		*FRONT SIGNAL LAMP (LH)	Cut	97.00 FL	*97.00 FL
7	2		*FRONT FOOTREST (RH) & (LH)	N/S Twisted / O/S Broken	140.00 FL	*140.00 FL
8	1		*FRONT FOOTREST BRACKET (LH)	Bent	135.00 FL	*135.00 FL
9	1		*FRONT FOOTREST BRACKET (RH)	Bent	135.00 FL	*135.00 FL
10	1		*GEAR PEDAL	Bent	95.00 FL	*95.00 FL
11	1		*BRAKE PEDAL	Bent	105.00 FL	*105.00 FL
12	1		*SET ENGINE GUARD	Cut	330.00 FL	*330.00 FL
13	1		*REAR FOOTREST (RH)	Cut	70.00 FL	*70.00 FL
14	1		*EXHAUST COVER -A	Cut	48.00 FL	*48.00 FL
15	1		*EXHAUST COVER -B	Cut	110.00 FL	*110.00 FL
16	1		*FRONT FENDER	Cut	190.00 FL	*190.00 FL
17	1		*TANK COVER (LH)	Cut	195.00 FL	*195.00 FL
18	1		*TANK COVER PANEL (LH)	Cut	145.00 FL	*145.00 FL
19	1		*COVER (LH)	Repair	175.00 FL	*- FL
20	1		*COVERINNER PANEL (LH)	Deformed	105.00 FL	*105.00 FL
21	1		*FORK (LH) (LOCAL REPAIR)	Cut	531.00 FS	*100.00 FS
22	1		*VISOR	Cut	148.00 FL	*148.00 FL
23	1		*HEADLAMP LED	Cut	425.00 FL	*425.00 FL
24	1		*HEADLAMP PANEL	Cut	95.00 FL	*95.00 FL
25	1		*HEADLAMP BRACKET	Repair	165.00 FL	*- FL
26	1		*SIGNAL HOLDER COVER (LH)	Cut	95.00 FL	*95.00 FL
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	4,188.00	3,320.00
	- List Item Discount on L Items 10.00/10.00% (S\$)				365.70	322.00
				Total Parts (S\$)	3,822.30	2,998.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			*
1	TRANSPORT FEE	New	70.00	0.00
2	LABOUR CHARGE	New	250.00	220.00
		Gross Labour Cost (S\$)	320.00	220.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >