

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000753/ATY3E2

Date: 05/05/2022

REFERENCE

Insured/Claimant:	LEONG XIANRONG TIMOTHY	Policy No:	7210067109	
Date of Loss:	19/01/2022	Nature of Claim:	OD	Claim No: 7163336247SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBY2222H	Engine No:	DEM027403
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF48MN004590
Reg. Date:	30/06/2021 (Man. Year: 2020)	Odometer:	8809 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,395.00	15,957.12	24,437.88	60.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,652.00	4,782.00	8,870.00	64.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	54,047.00	20,739.12	33,307.88	61.63
+ GST 7.00/7.00% (S\$)	3,783.29	1,451.74	2,331.55	61.63
Nett Amount (S\$)	57,830.29	22,190.86	35,639.43	61.63

INSPECTION

Date of Assignment:	21/01/2022		
Date Inspected:	20/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Damaged	293.00 FS	*234.00 FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	102.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	Not Necessary	293.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Missing	302.00 FS	*120.40 FS
9	2		*FRONT BUMPER AIR GRILLE TRIM - LH / RH	Not Necessary	108.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,754.00 FS	*1,403.20 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	212.00 FS	*169.20 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
13	1		*FRONT BUMPER BRACKET - RH	Damaged	254.00 FS	*203.20 FS
14	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Deformed	143.00 FS	*114.00 FS
16	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
17	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
18	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	154.00 FS	*122.80 FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	64.00 FS	*51.04 FS
20	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
21	1		*HORN - RH	Not Necessary	139.00 FS	*- FS
22	1		*HORN SUPPORT - RH	Not Necessary	33.00 FS	*- FS
23	3		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	488.00 FS	*- FS
24	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
25	1		*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
26	2		*FRONT FENDER - LH / RH	Not Necessary	2,454.00 FS	*- FS
27	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	162.00 FS	*- FS
28	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	82.00 FS	*- FS
29	12		*POP RIVET	Not Necessary	46.00 FS	*- FS
30	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	264.00 FS	*- FS
31	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	518.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
33	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	164.00 FS	*- FS
34	2		*FRONT WHEEL SPOILER LOWER - LH / RH	Not Necessary	79.00 FS	*- FS
35	2		*FRONT FENDER LEDGE COVER LONG - LH / RH	Not Necessary	70.00 FS	*- FS
36	2		*HEADLAMPS COVER - LH / RH	Not Necessary	98.00 FS	*- FS
37	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
38	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
39	2		*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
40	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
41	1		*BONNET STRIKER - LH / RH	O/S Bent	112.00 FS	*44.56 FS
42	2		*BONNET LOCK	Not Necessary	455.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
44	1		*BONNET RELEASE CABLE	Bent	64.00 FS	*50.56 FS
45	1		*BONNET RELEASE LEVER	Cracked	15.00 FS	*11.84 FS
46	1		*PLENUM CHAMBER	Not Necessary	108.00 FS	*- FS
47	2		*HEADLIGHT - LH / RH	O/S Cracked	16,344.00 FS	*6,537.60 FS
48	2		*LIFT CYLINDER - LH / RH	Not Necessary	462.00 FS	*- FS
49	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
50	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
51	2		*LOCK CARRIER SUPPORT - LH / RH	Not Necessary	85.00 FS	*- FS
52	1		*CHARGED AIR COOLER	Dented	654.00 FS	*522.80 FS
53	1		*AIR COOLER PRESSURE HOSE - RH	Not Necessary	413.00 FS	*- FS
54	1		*A/C CONDENSER	Dented	683.00 FS	*546.00 FS
55	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR	Not Necessary	1,010.00 FS	*- FS
57	1		*RADIATOR COOLANT (6PCS)	Necessary	282.00 FS	*37.60 FS
58	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	102.00 FS	*40.08 FS
59	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Cracked	38.00 FS	*14.64 FS
60	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
61	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
62	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
63	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
64	1		*SUNDRIES	Necessary	350.00 FS	*26.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	40,395.00	15,957.12
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHANGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS	New	1,900.00	980.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDER	New	4,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILIATE RENEWAL OF FRONT REINFORCEMENT BEAM BRACKET (Supplementary)	New	780.00	780.00
Gross Labour Cost (S\$)			13,652.00	4,782.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >