

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000762/KTY3N2**Date:** 16/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00073792101

**Claimant Vehicle No :** SKZ3543M **Insured Vehicle No :** GBK4414G

Date of Loss: 13/01/2022 Nature of Claim: TP Claim No: SNM22D200347/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ3543M**

Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27091030784331

Reg. Date: 20/01/2016 (Man. Year: 2015) Chassis No: WDD1173422N278119

Colour: White Odometer: 143239 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 5,935.54          | 3,721.36          | 2,214.18          | 37.30         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 1,660.00          | 490.00            | 1,170.00          | 70.48         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>7,595.54</b>   | <b>4,211.36</b>   | <b>3,384.18</b>   | <b>44.55</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>3,350.00</b>   |                   |               |
| <b>(\$\$)</b>                             | 7,595.54          | 3,350.00          | 4,245.54          | 55.90         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 531.69            | 234.50            | 297.19            | 55.90         |
| <b>Nett Amount (\$\$)</b>                 | <b>8,127.23</b>   | <b>3,584.50</b>   | <b>4,542.73</b>   | <b>55.90</b>  |

INSPECTION

Date of Assignment: 13/03/2022

Date Inspected: 24/01/2022 Inspected At: Sin Ming Autocare BFG Pte Ltd (HQ)  
176, Sin Ming Drive #02-05, Sin Ming Autocare Complex  
Singapore 575721

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 16 Mar 2022)                |
| <b>Parts:</b>        | 143  | MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                            |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKZ3543M)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition   | Repairer's | Amount       |
|-----|-----|----------|-------------------------------|-------------|------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                 | Cracked     | 1,407.64 F | *1,421.95 FL |
| 2   | 10  |          | *FRONT BUMPER CLIPS           | Necessary   | 80.00 F    | *80.00 FL    |
| 3   | 1   |          | *FRONT BUMPER SIDE BRACKET RH | Serviceable | 158.50 F   | *- FL        |
| 4   | 1   |          | *FRONT BUMPER SIDE BRACKET LH | Serviceable | 158.50 F   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER NOZZLE MOTOR RH | Serviceable | 285.15 F   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER NOZZLE COVER RH | Serviceable | 108.25 F   | *- FL        |
| 7   | 1   |          | *FRONT HEADLAMP RH            | Cut         | 3,503.50 F | *2,632.90 FL |
| 8   | 1   |          | *FRONT BUMPER SIDE SENSOR RH  | Serviceable | 234.00 FS  | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>5,935.54</b> | <b>4,134.85</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | 0.00            | 413.49          |
| <b>Total Parts (\$\$)</b>                                 | <b>5,935.54</b> | <b>3,721.36</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount        |
|--------------------------------|---|----------|-----------------|---------------|
| <b>Labour Items</b>            |   |          |                 |               |
| 1                              | TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY | New      | 700.00          | 220.00        |
| 2                              | TO PUTTY,APPLY PRIMER & SPRAY PAINT FENDER RH,FRONT BUMPER      | New      | 800.00          | 250.00        |
| 3                              | TO CHECK WIRING FUNCTIONS                                       | New      | 80.00           | 20.00         |
| 4                              | COMPUTER PROGRAMME  | New      | 80.00           | 0.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>1,660.00</b> | <b>490.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >