

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000763/ETY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00023762100

Claimant Vehicle No : SLK3541K **Insured Vehicle No :** GBL524T

Date of Loss: 18/01/2022 Nature of Claim: TP Claim No: SNM22D200519/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK3541K**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR990124

Reg. Date: 13/01/2017 (Man. Year: 2016) Chassis No: JTDKB3FU603543723

Colour: Silver Odometer: 299253 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Toyo 4 mm Rear Left Side: Toyo 4 mm

Front Right Side: Toyo 4 mm Rear Right Side: Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,409.50	8,340.90	4,068.60	32.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,982.40	9,986.40	5,996.00	37.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	28,391.90	18,327.30	10,064.60	35.45
+ GST 7.00/7.00% (\$\$)	1,987.43	1,282.91	704.52	35.45
Nett Amount (\$\$)	30,379.33	19,610.21	10,769.12	35.45

INSPECTION

Date of Assignment: 21/01/2022

Date Inspected: 21/01/2022 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 11.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3541K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER RR BUMPER	Broken	469.50 FS	*469.50 FS
3	1		*RETAINER ,RR BUMPER	Broken	124.90 FS	*124.90 FS
4	1		*RETAINER ,RR BUMPER	Not Necessary	123.60 FS	*- FS
5	1		*SEAL ,RR BUMPER	Missing	93.50 FS	*93.50 FS
6	1		*SEAL ,RR BUMPER	Not Necessary	93.50 FS	*- FS
7	1		*REINFORCEMENT	Not Necessary	353.10 FS	*- FS
8	1		*GUARD,RR BUMPER	Cut	611.30 FS	*611.30 FS
9	1		*FILLER ,RR BUMPER	Missing	131.10 FS	*131.10 FS
10	1		*FILLER ,RR BUMPER	Not Necessary	131.10 FS	*- FS
11	1		*PANEL SUB-ASSY ,BODY	Dented	689.70 FS	*689.70 FS
12	1		*PAD ,RR FLOOR	Repair	618.90 FS	*- FS
13	1		*COVER ,FLOOR UNDER	Crushed	185.60 FS	*185.60 FS
14	1		*CLIP	Necessary	3.50 FS	*3.50 FS
15	1		*COVER ,FLOOR UNDER	Not Necessary	256.50 FS	*- FS
16	1		*PANEL SUB-ASSY	Dented	925.90 FS	*925.90 FS
17	1		*PANEL S/A QTR W/H	Not Necessary	576.20 FS	*- FS
18	1		*LINER ,RR WHEEL	Cut	148.00 FS	*148.00 FS
19	1		*PANEL ,QUARTER WHEEL	Not Necessary	314.20 FS	*- FS
20	1		*PANEL SUB-ASSY	Not Necessary	925.90 FS	*- FS
21	1		*PANEL BONDING AD	Not Necessary	267.20 FS	*- FS
22	1		*DUCT ASSY ,QUARTER	Crushed	70.90 FS	*70.90 FS
23	1		*PROTECTOR ,QUARTER	Necessary	24.40 FS	*24.40 FS
24	1		*COVER SUB-ASSY	Not Necessary	219.50 FS	*- FS
25	1		*LENS & BODY ,RR	Broken	479.30 FS	*479.30 FS
26	1		*COVER ,RR	Cut	68.50 FS	*68.50 FS
27	1		*LENS & BODY ,RR	Broken	532.00 FS	*532.00 FS
28	1		*PANEL SUB-ASSY ,RR	Dented	1,371.80 FS	*1,371.80 FS
29	1		*MOULDING ,RR DOOR	Not Necessary	97.90 FS	*- FS
30	1		*MOULDING ,RR DOOR	Not Necessary	41.00 FS	*- FS
31	1		*EMBLEM SUB-ASSY	Necessary	76.00 FS	*76.00 FS
32	1		*PLATE ,LUGGAGE COMPT	Necessary	58.00 FS	*58.00 FS
33	1		*PLATE ,LUGGAGE COMPT	Necessary	58.00 FS	*58.00 FS
34	1		*WHEEL, DISC	Cut	1,995.20 FS	*1,995.20 FS
35	1		*GRAB DUNLOP 195-65R15	Torn	88.00 FS	*88.00 FS
36	1		*STRIPE RR DOOR	Necessary	23.20 FS	*23.20 FS
37	1		*STRIPE RR DOOR	Necessary	37.00 FS	*37.00 FS
38	1		*STRIPE RR DOOR	Necessary	16.30 FS	*16.30 FS
39	2		*GUIDE ,RR	Necessary	7.40 FS	*7.40 FS
40	1		*GROMMET ,SCREW	Necessary	1.90 FS	*1.90 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **12,409.50** **8,340.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR RH TYRE AND SPORT -RIM TO BALANCE	New	180.00	144.00
2	SUPPLY SEALANT FOR REAR RH DOOR	New	60.00	60.00
3	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
4	TO CONDUCT WHEEL ALIGNMENT CHECK	New	180.00	180.00
5	R/I REAR SUSPENSION TO CHECK AND REPLACE NECESSARY PARTS	New	1,440.00	0.00
6	TO CHECK WIRING AND LIGHTING TO WATER TEST FOR LEAK	New	122.40	122.40
7	R/I REAR CARPET ,TRIMMINH ,REAR SEATS AND ALL OTHER ATTACHMENT TO FACILITATE REPAIRS	New	720.00	720.00
8	TO REPLACE REAR ACCIDENT DAMAGE PARTS STRAIGHTEN /REALIGN ALL OTHER AFFECTED AREAS	New	7,200.00	5,040.00
9	TO SPRAY PAINT OH REAR ACCIDENT AFFECTED AREAS	New	5,900.00	3,540.00
Gross Labour Cost (\$\$)			15,982.40	9,986.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >