

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000764/UVY3N2**Date:** 22/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00143082100

**Claimant Vehicle No :** SKH1180J **Insured Vehicle No :** SMZ6752H

Date of Loss: 14/01/2022 Nature of Claim: TP Claim No: SNM22D200413/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH1180J**

Make & Model: HONDA STREAM, 1.7 (A) Engine No: R18A1726792

Reg. Date: 14/03/2007 (Man. Year: 2006) Chassis No: RN61023690

Colour: White Odometer: 186691 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/65R15 Rear Tyre Size: 205/65R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,569.14	1,151.60	7,417.54	86.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	1,550.00	1,360.00	46.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>11,479.14</b>	<b>2,701.60</b>	<b>8,777.54</b>	<b>76.47</b>

INSPECTION

Date of Assignment: 21/01/2022

Date Inspected: 19/01/2022 Inspected At: My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ)  
60 Jalan Lam Huat, Carros Centre #05-21  
Singapore 737869

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

NOTE: THE VEHICLE HAS NOT SEND IN FOR REPAIR

MARKET VALUE:: \$2,800.00-LTA REIMBURSEMENT VALUE: \$730.00=NETT VALUE \$2,070.00

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2022)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKH1180J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,573.20 FL	*- FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	376.60 FL	*- FL
3	1		*TAILGATE OUTER LOCK HANDLE	Not Necessary	164.40 FL	*- FL
4	1		*TAILGATE LOGO	Not Necessary	62.40 FL	*- FL
5	1		*TAILGATE EMBLEM STREAM	Serviceable	51.90 FL	*- FL
6	1		*TAILGATE INNER LOCK	Serviceable	485.90 FL	*- FL
7	1		*TAILGATE WEATHER STRIP	Serviceable	210.40 FL	*- FL
8	1		*TAILGATE INNER HANDLE	Serviceable	97.00 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	624.00 FL	*- FL
10	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	164.00 FL	*- FL
11	1		*TAILLAMP RH	Cracked	497.60 FL	*386.40 FL
12	4		*TAILLAMP BOLT COVER	Not Necessary	100.00 FL	*- FL
13	2		*TAILLAMP PANEL	Repair	704.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	688.90 FL	*688.90 FL
15	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	19.20 FL	*- FL
16	1		*REAR BUMPER SIDE RETAINER	O/s Bent	128.40 FL	*64.20 FL
17	1		*REAR FENDER INNER COWLING RH	Not Necessary	235.00 FL	*- FL
18	1		*REAR FENDER INNER TRIM RH	Not Necessary	697.10 FL	*- FL
19	1		*REAR FENDER AIR VENT	Not Necessary	69.20 FL	*- FL
20	1		*REAR END PANEL	Repair	658.00 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Serviceable	265.80 FL	*- FL
22	1		*REAR FLOOR PANEL COVER BOARD RH	Not Necessary	394.20 FL	*- FL
23	1		*REAR JACK COVER GARNISH	Not Necessary	197.10 FL	*- FL
24	1		*REAR EXHAUST PIPE	Not Necessary	954.00 FL	*- FL
25	8		*REAR BUMPER CLIPS	Necessary	52.00 FS	*40.00 FS
26	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	130.00 FS	*- FS
27	3		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.50 FS	*- FS
28	6		*TAILGATE OUTER GARNISH CLIP	Not Necessary	39.00 FS	*- FS
29	10		*TAILGATE INNER BOARD CLIP	Not Necessary	65.00 FS	*- FS
30	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
32	4		*TAILLAMP CLIP	Not Necessary	34.00 FS	*- FS
33	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	39.00 FS	*- FS
34	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
35	1		*REAR END PANEL BOTTOM EXTENSION SEALANT	Not Necessary	60.00 FS	*- FS
36	1		*SET REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,452.80</b>	<b>1,379.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,883.66	227.90
<b>Total Parts (\$\$)</b>	<b>8,569.14</b>	<b>1,151.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT,REMOVE AND REPLACE PARTS	New	1,000.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	800.00
3	TUFF COAT	New	200.00	0.00
4	WIRING AND BULB CHECK	New	80.00	20.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	350.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANFER TAILGATE MECHANISM	New	80.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,910.00</b>
				<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >