

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22000774/KPA3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100417623
<b>Claimant Vehicle No :</b>	SGD4466J	<b>Insured Vehicle No :</b>	SBV2121G
Date of Loss:	19/01/2022	Nature of Claim:	TP
		Claim No:	6803541060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGD4466J</b>	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3, 2.0 E (A)	Chassis No:	LRW3F7FA1MC385378
Reg. Date:	24/11/2021 (Man. Year: 2021)	Odometer:	5156 km
Colour:	Metallic Red		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,394.81	4,993.28	1,401.53	21.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,390.00	1,560.00	52.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,344.81</b>	<b>6,383.28</b>	<b>2,961.53</b>	<b>31.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	654.14	446.83	207.31	31.69
<b>Nett Amount (S\$)</b>	<b>9,998.95</b>	<b>6,830.11</b>	<b>3,168.84</b>	<b>31.69</b>
<b>+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		513.60		
		<b>Nett Liability (S\$)</b>	<b>7,343.71</b>	
		<b>Global Sum Settlement (S\$)</b>	<b>7,300.00</b>	

INSPECTION

Date of Assignment:	21/01/2022	
Date Inspected:	21/01/2022	Inspected At: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Dented	763.55 FL	*763.55 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Repair	29.33 FL	*- FL
3	1		*FRONT FENDER BRACKET RH	Repair	21.83 FL	*- FL
4	1		*FRONT BUMPER UNDERCOVER	Cracked	216.92 FL	*216.92 FL
5	1		*HEADLAMP RH	Mtg Cracked	1,308.41 FL	*1,308.41 FL
6	1		*HEADLAMP BRACKET RH	Serviceable	65.93 FL	*- FL
7	1		*FOG LAMP ASSY RH	Serviceable	291.03 FL	*- FL
8	1		*FRONT FENDER RH	Repair	548.60 FL	*- FL
9	2		*FRONT SENSORS	Shorted	397.76 FL	*397.76 FL
10	2		*FRONT SENSORS HOLDER	Necessary	41.34 FL	*41.34 FL
11	1		*FRONT RIM 19 INCH	Dented	978.50 FL	*978.50 FL
12	1		*FRONT FENDER SHIELD RH	Cracked	176.82 FL	*176.82 FL
13	1		*FRONT KNUCKLE ARM RH	Bent	520.56 FL	*520.56 FL
14	1		*FRONT BEARING HUB RH	Necessary	189.53 FL	*189.53 FL
15	1		*FRONT UPPER CONTROL ARM RH	Distorted	156.82 FL	*156.82 FL
16	1		*FRONT LOWER ARM RH	Bent	264.30 FL	*264.30 FL
17	1		*FRONT LOWER LATERAL LINK RH	Distorted	283.64 FL	*283.64 FL
18	1		*FRONT SWAYBAR LINKAGE RH	Serviceable	18.13 FL	*- FL
19	1		*STEERING GEAR TIE ROD RH	Serviceable	171.50 FL	*- FL
20	1		*FRONT DAMPER RH	Serviceable	277.57 FL	*- FL
21	1		*FRONT FOG LAMP COVER RH	Dented	16.54 FL	*16.54 FL
22	1		*FRONT BUMPER SPONGE	Cracked	66.73 FL	*66.73 FL
23	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*100.00 FS
24	1		*FRONT UNDER COVER CLIPS	Not Necessary	120.00 FS	*- FS
25	1		*FRONT INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,075.34</b>	<b>5,531.42</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	680.53	538.14
<b>Total Parts (\$\$)</b>	<b>6,394.81</b>	<b>4,993.28</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR FRONT ACCIDENT AREA	New	1,000.00	480.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AR	New	1,000.00	480.00
3	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	250.00	200.00
4	TO CONDUCT WHEEL ALIGNMENT AND BALANCING	New	150.00	60.00
5	TO CHECK WIRING ELECTRICAL SYSTEM & ETC	New	200.00	20.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	350.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,950.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >