

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000778/ETY3Q2**Date:** 04/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00020542100

Claimant Vehicle No : SLF1213Y **Insured Vehicle No :** SGQ9391P

Date of Loss: 19/01/2022 Nature of Claim: TP Claim No: SNM22D200532/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF1213Y**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX749091

Reg. Date: 20/05/2008 (Man. Year: 2008) Chassis No: MR053HY9305062812

Colour: Beige Odometer: 172210 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17

Front Left Side: Firestone 4 mm Rear Left Side: Firestone 4 mm

Front Right Side: Firestone 4 mm Rear Right Side: Firestone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,465.20	6,201.17	13,264.03	68.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	3,230.00	2,310.00	41.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,005.20	9,431.17	15,574.03	62.28
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	25,005.20	6,000.00	19,005.20	76.00

INSPECTION

Date of Assignment: 21/01/2022

Date Inspected: 24/01/2022 Inspected At: 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807

Estimated Period of Repair: 12.0 days Repairer: Nineteen Autowerks Pte Ltd - Woodlands (HQ)

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1213Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	798.40 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	295.20 FL	*- FL
3	1		*BONNET HINGE L/R	Bent	390.40 FL	*216.00 FL
4	1		*BONNET OUTER SEAL	Not Necessary	128.70 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	225.70 FL	*- FL
6	1		*FR BUMPER	Broken	721.40 FL	*483.00 FL
7	1		*FR BUMPER REINFORCEMENT	Dented	499.20 FL	*381.00 FL
8	1		*LH FR BUMPER RETAINER	Broken	128.50 FL	*70.00 FL
9	1		*RH FR BUMPER RETAINER	Broken	128.50 FL	*70.00 FL
10	1		*FRT BUMPER GRILLE	Not Necessary	598.70 FL	*- FL
11	1		*FR BUMPER LOGO	Necessary	120.50 FL	*65.00 FL
12	1		*FR BUMPER LOWER GRILLE	Not Necessary	315.20 FL	*- FL
13	1		*LH FR BUMPER SIDE GRILLE	Not Necessary	89.70 FL	*- FL
14	1		*FR BUMPER LOWER COVER	Not Necessary	187.90 FL	*- FL
15	1		*RH FR FOG LIGHT GARNISH CHROME	Not Necessary	97.60 FL	*- FL
16	1		*LH FR FOG LIGHT GARNISH CHROME	Not Necessary	97.60 FL	*- FL
17	1		*LH HEADLIGHT	Broken	602.80 FL	*602.80 FL
18	1		*LH HEADLIGHT SUPPORT PANEL	Dented	187.90 FL	*187.90 FL
19	1		*RH HEADLIGHT	Broken	602.80 FL	*602.80 FL
20	1		*RH HEADLIGHT SUPPORT PANEL	Dented	187.90 FL	*187.90 FL
21	1		*FR SUPPORT PANEL	Dented	684.50 FL	*350.00 FL
22	1		*FR SUPPORT PANEL TOP GARNISH	Broken	97.60 FL	*97.60 FL
23	1		*AIRCON CONDENSER	Not Necessary	984.50 FL	*- FL
24	1		*RADIATOR	Not Necessary	754.80 FL	*- FL
25	1		*RADIATOR TOP GARNISH	Not Necessary	269.70 FL	*- FL
26	1		*REAR BOOTLID	Dented	985.90 FL	*794.00 FL
27	1		*REAR BOOTLID RUBBER	Crushed	212.20 FL	*212.20 FL
28	1		*REAR BOOTLID LOCK	Bent	152.20 FL	*152.20 FL
29	1		*REAR BOOTLID LOCK CATCH	Not Necessary	82.50 FL	*- FL
30	2		*REAR BOOT HINGE	Not Necessary	170.00 FL	*- FL
31	1		*REAR BOOT CENTRE GARNISH	Broken	185.20 FL	*185.20 FL
32	1		*REAR BOOT CENTRE GARNISH EMBLEM	Necessary	42.50 FL	*42.50 FL
33	1		*REAR BOOT EMBLEM (VIOS)	No Fitted	42.50 FL	*- FL
34	1		*REAR BOOT EMBLEM (E)	Necessary	42.50 FL	*42.50 FL
35	2		*REAR TAIL LAMP	Broken	771.60 FL	*771.60 FL
36	1		*REAR TAIL LAMP PANEL	Repair	470.00 FL	*- FL
37	1		*REAR TAIL LAMP GASKET	Not Necessary	70.40 FL	*- FL
38	1		*REAR END PANEL	Dented	695.00 FL	*590.00 FL
39	1		*REAR END PANEL TOP GARNISH	Cut	76.30 FL	*76.30 FL
40	2		*REAR FENDER	Repair	1,970.40 FL	*- FL
41	2		*REAR FENDER INNER GARNISH	Not Necessary	754.00 FL	*- FL
42	1		*REAR FENDER AIR DUCT LH	Not Necessary	42.70 FL	*- FL
43	1		*REAR FENDER UNDER SHIELD (LH)	Missing	76.40 FL	*76.40 FL
44	1		*REAR SPARE TYRE PANEL	Not Necessary	1,012.20 FL	*- FL
45	1		*REAR SPARE TYRE PANEL TOP CENTRE COVER BOARD	Not Necessary	195.60 FL	*- FL
46	2		*REAR SPARE TYRE PANEL TOP SIDE TRAY	Not Necessary	402.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NUMBER PLATE LAMP (LH)	N/S Broken	131.20 FL	*65.60 FL
48	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.00 FL	*- FL
49	1		*REAR BUMPER	Dented	785.60 FL	*545.00 FL
50	2		*REAR BUMPER SIDE RETAINER	Broken	91.00 FL	*91.00 FL
51	2		*REAR BUMPER BRACKET	Broken	96.40 FL	*96.40 FL
52	1		*REAR EXHAUST CHASSIS BEAM	Not Necessary	365.20 FL	*- FL
53	1		*REAR SPARE TYRE PANEL SIDE PANEL	Not Necessary	130.40 FL	*- FL
54	2		*REAR BUMPER REFLECTOR	Not Necessary	105.40 FL	*- FL
55	1		*RR AXLE	Not Necessary	1,380.00 FL	*- FL
56	1		*LH REAR WHEEL BEARING	Not Necessary	486.00 FL	*- FL
57	1		*LH REAR SHOCK ABSORBER	Not Necessary	180.00 FL	*- FL
58	1		*RH REAR WHEEL BEARING	Not Necessary	486.00 FL	*- FL
59	1		*RH REAR SHOCK ABSORBER	Not Necessary	180.00 FL	*- FL
60	1		*FR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
61	1		*RR FR FENDER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
62	1		*LH FR FENDER SHIELD CLIP	Necessary	50.00 FS	*10.00 FS
63	1		*BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
64	1		*FR BUMPER NO PLATE W CASING	Not Necessary	50.00 FS	*- FS
65	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
66	1		*END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
67	1		*REAR NO PLATE W CASING	Not Necessary	50.00 FS	*- FS
68	1		*REVERSE SENSOR	Broken	300.00 FS	*200.00 FS
69	1		*END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
70	1		*ENGINE COOLANT	Not Necessary	85.00 FS	*- FS
71	1		*BOOTLID SPOILER	Broken	800.00 FS	*300.00 FS
72	1		*FR BUMPER LOWER	Not Necessary	600.00 FS	*- FS
73	1		*RR BUMPER LOWER	Broken	600.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,998.60	7,964.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,533.40	1,763.73
Total Parts (\$\$)	19,465.20	6,201.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS	New	2,500.00	1,200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	1,800.00	1,600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	30.00
4	TO SUPPLY UNDER COATING /PUTTY ON PARTS REPLACED	New	50.00	30.00
5	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	80.00	30.00
6	TO CHECK WIRING & LIGHTING SYSTEM	New	80.00	30.00
7	RE-ADJUST WHEEL ALIGNMENT	New	100.00	60.00
8	TO REMOVE & FIT FR UNDERCARRIAGE	New	150.00	0.00
9	TO REMOVE & REFIT REVERSE SENSOR	New	80.00	30.00
10	TO REMOVE AND REFIT REAR TRIM ,GARNISH ASSY	New	250.00	50.00
11	TO REMOVE AND REFIT AIRCON CONDENSER ,RADIATOR ASSY	New	250.00	50.00
12	TO TOP UP 134A REFRIGERANT	New	150.00	120.00
Gross Labour Cost (\$\$)			5,540.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >