

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	GREAT AMERICA	N INSURANCE COMPANY		Ref:	CS3/GAI22000779/Vvf3e2
	3 TEMASEK AVEN TOWER SINGAPO	IUE #16-01 CENTENNIAL RE 039190		Date:	09/02/2022
				Code:	GAI
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	PA 6585U	Veh. Inspected	t	FBN 7600A
	Policy No.		Coverage (\$)		0.00
	Claim No.	CLMOMVC000004108	Excess (\$)		0.00
	Assign From	JANELLE TAN	Assign Date		21/01/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB150R	c.c		149
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	MLHKC2886J5029574	Colour		BLACK
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	110/70 R17	METZELER		7 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	110/70 R17	METZELER		7 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY PORTION.			R	
5. General Information					
	Accident Date	12/01/2022	Inspect Date /	Time	24/01/2022 (11:00 AM)
	Survey held at CANDYMOTOR WORKSHOP PTE LTD				
	25 KAKI BUIKIT ROAD 4 #01-83 SYNERGY @ KB SINGAPORE 417800				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
	Estimate Days of Repair				
5b.		Estimate	Days of Repair	·	

Report Ref No. CS3/GAI22000779/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser