

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000780/ATY3M4**Date:** 03/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00095132100

Claimant Vehicle No : SJH1603T **Insured Vehicle No :** YN8519Z

Date of Loss: 20/01/2022 Nature of Claim: TP Claim No: SNM22D200533/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH1603T**

Make & Model: TOYOTA RUSH, 1.5 (A) Engine No: 3SZ2132011

Reg. Date: 28/07/2008 (Man. Year: 2008) Chassis No: J200E0022405

Colour: White Odometer: 139768 km

Engine Capacity: 1495 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,710.00	6,520.75	15,189.25	69.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,200.00	2,430.00	4,770.00	66.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,910.00	8,950.75	19,959.25	69.04
Approved Total (Overridden) (\$\$)		7,100.00		
Nett Amount (\$\$)	28,910.00	7,100.00	21,810.00	75.44

INSPECTION

Date of Assignment: 24/01/2022

Date Inspected: 21/01/2022 Inspected At: SOON SENG COMPANY (SG) PTE LTD (HQ)
160 SIN MING DRIVE, #04-05 SIN MING
AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2022)
Parts:	M1-SUV	TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH1603T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,300.00 F	*830.00 FL
2	1		*BUMPER TOWING COVER	Deformed	110.00 F	*35.00 FL
3	10		*BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
4	2		*BUMPER RETAINERS	Necessary	200.00 F	*110.00 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	170.00 F	*- FL
6	1		*BOOT LID	Distorted	1,620.00 F	*1,404.00 FL
7	1		*REAR LOGO	Necessary	120.00 F	*65.00 FL
8	1		*BOOT TOP SPOILER ASSEMBLY	Not Necessary	700.00 F	*- FL
9	1		*REAR BOOT 3RD BRAKE LIGHT	Not Necessary	350.00 F	*- FL
10	20		*FENDER CLIPS	Not Necessary	60.00 F	*- FL
11	1		*REAR EMBLEM	Repeated	90.00 F	*- FL
12	1		*REAR END PANEL	Distorted	950.00 F	*481.00 FL
13	1		*BOOT LOCK	Damaged	420.00 F	*285.00 FL
14	1		*BOOT LATCH	Not Necessary	200.00 F	*- FL
15	2		*BOOT HINGE	Not Necessary	680.00 F	*- FL
16	1		*BOOT SPARE TYRE COVER	Distorted	850.00 F	*850.00 FL
17	1		*BOOT SPARE TYRE MOUNTING BRACKET	Not Necessary	740.00 F	*- FL
18	1		*SPARE TYRE	Not Necessary	400.00 F	*- FL
19	1		*REAR WIPER MOTOR	Not Necessary	550.00 F	*- FL
20	1		*REAR WIPER ASSEMBLY	Not Necessary	500.00 F	*- FL
21	1		*BOOT INNER GARNISH	Deformed	420.00 F	*420.00 FL
22	1		*BOOT INNER RUBBER	Cut	400.00 F	*240.00 FL
23	1		*REAR OUTER TAIL LIGHTS	O/s Cracked	960.00 F	*480.00 FL
24	1		*REAR REINFORCEMENT BAR	Not Necessary	800.00 F	*- FL
25	1		*REAR EXHAUST MUFFLER	Not Necessary	1,600.00 F	*- FL
26	4		*REAR EXHAUST RUBBER MOUNTS	Not Necessary	380.00 F	*- FL
27	1		*REAR WINDSCREEN WITH DEMIST FUNCTION	Shattered	1,400.00 F	*1,185.00 FL
28	1		*WINDSCREEN MOULDING	Necessary	500.00 F	*148.00 FL
29	3		*END PANEL AND WINDSCREEN GUM	Necessary	360.00 F	*120.00 FL
30	2		*REAR FENDER LH & RH	Repair	2,600.00 F	*- FL
31	1		*INNER BOOT FLOORBOARD PANEL	Buckled	1,100.00 F	*1,100.00 FL
32	1		*LICENSE PLATE LIGHT MODULE	Damaged	190.00 F	*58.00 FL
33	1		*REVERSE PDC SENSORS (SET OF 2)	Damaged	400.00 FS	*200.00 FS
34	1		*IROAD REAR RECORDING CAMERA	Damaged	450.00 FS	*380.00 FS
35	1		*NEW NUMBER PLATE WITH CASING	Bent	90.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,710.00	8,481.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,960.25
Total Parts (S\$)	21,710.00	6,520.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND SYSTEM FUNCTION.	New	480.00	30.00
2	RUST PROOFING ON AFFECTED AREAS.	New	420.00	80.00
3	REMOVAL AND REFIT REAR WINDSCREEN.	New	500.00	120.00
4	LABOR TO REMOVE AND REFIT REAR BUMPER, BOOT, REVERSE SENSORS, END PANEL, REAR EXHAUST AND TAIL LIGHTS. INCLUDE PULLING OUT FRAME OF REAR UNDERCARRIAGE.	New	1,800.00	800.00
5	TO CUT AND WELD RH & LH FENDER, BOOT FLOORBOARD PANEL.	New	1,600.00	400.00
6	TO RESPRAY DAMAGED AND REFITTED PARTS (REAR BUMPER, SPOILER, REAR FENDERS, BOOT, INTERIOR OF REAR BOOT FRAME, END PANEL AND BOOT FLOORBOARD).	New	2,400.00	1,000.00
Gross Labour Cost (S\$)			7,200.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >