

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22000785/REA3Q2**Date:** 28/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100487625
Claimant Vehicle No :	SMB180Z	Insured Vehicle No :	GY1150D
Date of Loss:	23/12/2021	Nature of Claim:	TP
		Claim No:	4220562557SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB180Z	Engine No:	90292600910176
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Chassis No:	WEB62808323122689
Reg. Date:	18/11/2011 (Man. Year: 2011)	Odometer:	731688 km
Colour:	Multi-colour		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8/8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,917.44	2,117.91	5,799.53	73.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,414.00	1,057.00	357.00	25.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,331.44	3,174.91	6,156.53	65.98
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	9,331.44	2,750.00	6,581.44	70.53
+ Loss of Use (4.0 x S\$250.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,757.00		

INSPECTION

Date of Assignment:	19/01/2022	
Date Inspected:	19/01/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET :REAR BUMPER RH ,FOR MB CITARO O53	Necessary	45.51 F	*45.51 FL
2	1		*LAMP ,SIDE MARKET :FOR MB CITARO O530 BUS	Missing	94.50 F	*94.50 FL
3	1		*LAMP ,TAIL :REAR LH ,FOR MB CITARO O530	Cracked	1,261.71 F	*1,261.71 FL
4	2		*COUPLING :FOR MB CITARO O530	Necessary	18.78 F	*18.78 FL
5	2		*PIN,CHERIS:WITH HEAD ,FOR MB CITARO O530	Necessary	6.00 F	*6.00 FL
6	1		*BUMPER :REAR ,LH ,FOR MB CITARO O530	Missing	837.84 F	*837.84 FL
7	1		*FLAP :REAR END ,FOR MB CITARO BUS	Not Necessary	5,573.10 F	*- FL
8	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
9	1		*STICKER 60KM/H	Necessary	5.00 FS	*5.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)						7,917.44 2,344.34
- List Item Discount on L Items 0.00/10.00% (\$\$)						0.00 226.43
Total Parts (\$\$)						7,917.44 2,117.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	354.00	262.00
Gross Labour Cost (\$\$)			1,414.00	1,057.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >