

(08/11/13) wef

REF:

ASS. REC. BY: Ronan**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 1802at Workshop m/s SMRTof Go, now, run, Ltd PK 64

Insured:

ALH

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

SMB 1802

Yr Regn:

2011 / NBVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ CITARO 0532.c 6374

Colour

MULTI

A/C:

Insured / Std / NI / NA

Sp. Reading

731688

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WES 62808 323 122689Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

8/0

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

19/01/22

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS, SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

Report Format :

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 19/01/2022

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB180Z
Case Reference Number	BUS/12/21/7033
Registration Date	18/11/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARO O530
Name of Driver	Yeoh Kien Seng
Type of Accident	Side Swipe
Accident Date and Time	23/12/2021 8:32 AM
Accident Reported Date and Time	23/12/2021 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB180Z - Left rear brake light cover cracked, left rear bumper cracked PENDING TP DETAILS
Prepared Date and Time	12/1/2022 10:35 AM
Chassis Number	WEB62808323122689
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$354.00	\$0.00
Total Spare Part Cost	\$1,661.56	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,075.56	\$0.00
Lump Sum Total	\$3,100.00	\$0.00
Number of Repair Days	3.0	2 days
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	12/01/2022 10:45 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/01/2022

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	755
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$354.00	262
Total Spray Painting & Panel Beating	\$354.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	na
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	na
6010113	Body	6287502974	FLAP:REAR END, FOR MB CITARO BUS	1.00	\$5,573.10	100.00	\$0.00	Repair	R
6009887	ENGINE		PIN, CHERIS: WITH HEAD, FOR MB CITARO O530	2.00	\$3.00	10.00	\$5.40	Replace	na
6009888	ENGINE		COUPLING: FOR MB CITARO O530	2.00	\$9.39	10.00	\$16.90	Replace	na
6009879	VE	0008206864	LAMP, TAIL: REAR LH, FOR MB CITARO O530	1.00	\$1,261.71	10.00	\$1,135.54	Replace	ca
6010012	VE	0005446911	LAMP, SIDE MARKER: FOR MB CITARO O530 BUS	1.00	\$94.50	10.00	\$85.05	Replace	ms
6009908	BODY LH	6288850005	BUMPER: REAR, LH, FOR MB CITARO O530	1.00	\$837.84	10.00	\$754.06	Replace	ms
Total					\$7,859.54		\$2,076.95		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
19/01/2022
2 days
48
19/01/22 @ 15:00
Res after repair