

TP China  
Xiao Tong.

SJL8885D. 2008 Dec.

Mitsubishi Lancer 1998cc

JMYSTCY4A94000574

Front Bumper	Distorted	<del>1500(SN)</del> , 900(SN)
Front Bumper Lips.	New	30(SN) ✓
Front Bumper Side Holder LH.	Dark	42 ✓
Front Bumper Reinforcement.	NY	326 X
Front Bumper Sticker Wrap	New	<del>350(SN)</del> 250(SN)
Front Bumper Lower Spoiler LH		<del>1200(SN)</del> 800(SN)
Headlip LH.	Lt	1036 ✓
Headlip Outer Garish LH.	Lt	<del>150(SN)</del> , 80(SN)
Headlip Lower Bracket LH.	NY NW	68 X
Front LH Fender	Dented	496 ✓
Front LH Fender Inner Shield	Behind HS	✓
Front LH Fender Inner Shield Caps.	per	30(SN) ✓
Front LH Wheel Rim.	Lt	<del>800(SN)</del> 500(SN)
Front LH Tyre.	NY NW	300(SN) X

SJL8885D.

Front LH Shock Absorber	Best	<del>600(SN)</del> 400(SN)
Front LH lower Arm	Best	321 ✓
Front LH Knuckle Arm	MP M	35.8. X
Front LH Wheel Hub c/w Bearing	MP	235 ✓
Steering Rack and Pinion	MP M	1878. X

Panel Beating  
 Spray Painting.  
 Wiring  
 To remove front undercarriage  
 To perform wheel alignment.

<del>800</del>	500
<del>800</del>	400
<del>50</del>	30
<del>350</del>	200
<del>150</del>	80

Nett: 2275

Len 10%: 2047.50.

S-N: 2990

Labor: 1210

Total: 6297.50

A/S: 5K.

0.5 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

5,000  
 5 days