



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 586G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID (SN)	DENTED	1,239.35	1,239.35
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	483.40	-
1	RR BUMPER LH INNER SIDE GUIDE (SN)	NOT NECESSARY	161.15	-
1	RR BUMPER RH INNER SIDE GUIDE (SN)	NOT NECESSARY	161.15	-
1	REAR BUMPER TOWING FLAP EYE PRIMED (SN)	NOT NECESSARY	43.25	-
1	REAR BUMPER PANEL PRIMED (LINES PDC)(SN)	DENTED	1,035.00	1,035.00
1	SET MOUNTS PDC SENSOR REAR (SN)	NOT NECESSARY	61.80	-
1	LETTERING 216 I (SN)	NECESSARY	65.60	65.60
2	GROMMET (SN)	NECESSARY	1.60	1.60
1	PLAQUE 74MM (SN)	NECESSARY	72.85	72.85
1	REAR WINDOW (ESG)(SN)	NOT NECESSARY	620.90	-
1	REAR BUMPER TRIM STRIP CHROM (SN)	CUT	109.40	109.40
10	HOOK AND LOOP FASTENER (SN)	NOT NECESSARY	25.00	-
1	BOOTLID SEALING (SN)	NOT NECESSARY	144.55	-
4	DECOUPING RING PDC TORQUE CONVETER (SN)	NOT NECESSARY	20.60	-
4	ULTRASONIC SENSOR MINERALWEISS (WA96)(SN)	NOT NECESSARY	1,484.80	-
1	(DG) CLEANER R1 (100ML)(SN)	NECESSARY	26.15	26.15
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)(SN)	NECESSARY	263.10	263.10
1	(DG/SL) ADHESIVE PRIMER VP 206 (30ML)(SN)	NECESSARY	27.85	27.85
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
			6,197.50	2,990.90
<u>LABOUR</u>				
REPLACE REAR BOOT LID,REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC.			2,550.00	1,700.00
PAINTING REAR BOOT LID AND REAR BUMPER.			1,823.00	1,731.00
TO REPLACE REAR WINDSCREEN GLASS.			574.00	574.00
TO CONDUCT WATER LEAK TESTS.			75.00	75.00
TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.		NOT NECESSARY	531.00	-
TO REMOVE AND INSTALL REAR HAT-TRAY,REAR SEAT,CARPET AND ROOF TOP LINING TO FACILITATE REPAIR.		NOT NECESSARY	873.00	-

Report Ref No. CS/SMR22000787/Eqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	168.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	112.00
			6,898.00	4,528.00
GRAND TOTAL			13,095.50	7,518.90
RECOMMENDED COST OF REPAIRS				7,518.90

Report Ref No. CS/SMR22000787/Eqf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.