COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

KK-

DATE:

18-Jan-22

MODEL:

Hyundai i40

VEHICLE NO.: SHC3848R

INSURANCE: CHINA TAIPING

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Poor Pumper	1		\$552.00 °
	Rear Bumper			\$553.00
	Rear Bumper Under Cover	1		\$228.00 \$428.40
	Rear Bumper Reinforcement	1	00.00	
	Rear Bumper Clips	10	\$2.20	\$22.00
	SUB TOTAL			\$1,231.40
	LESS 20%			\$246.28
	DISCOUNTED TOTAL			\$985.12
	Rear Bumper Mat	1		\$50.00
	Reverse Sensors	1		\$246.28 \$985.12 \$50.00 \$135.70
	NETT TOTAL			\$185.70
	SPARE PARTS TOTAL			\$1,170.82
	Labour Charge			
	Panel Beating			\$300.00
	Spray Painting Charge			\$300.00
	R/I Reverse Sensors			\$120.00
	TOTAL LABOUR			\$720.00
	ESTIMATE TOTAL		-	\$1,890.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

> Theran Olyllay to. 10n 82135469 18/1/22 1600 Us atkriepuir phono wp 20lays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: