

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000790/ATY3N2**Date:** 06/05/2022**REFERENCE**

Insured/Claimant:	SAMANTHA LAW SIEW YEN	Policy No:	7210111716	
Date of Loss:	20/01/2022	Nature of Claim:	OD	Claim No: 9559343180SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCY1092K		
Make & Model:	AUDI A6, 2.0 TFSI MU S-LINE (C6) (A)	Engine No:	DKY015840
Reg. Date:	17/09/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF27MN094832
Colour:	Black	Odometer:	2782 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$230,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40R20	Rear Tyre Size:	255/40R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,892.00	3,873.20	1,018.80	20.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	972.00	652.00	320.00	32.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,864.00	4,525.20	1,338.80	22.83
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,264.00	3,925.20	1,338.80	25.43
+ GST 7.00/7.00% (S\$)	368.48	274.76	93.72	25.43
Nett Amount (S\$)	5,632.48	4,199.96	1,432.52	25.43

INSPECTION

Date of Assignment:	24/01/2022		
Date Inspected:	21/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING MIRROR MOUNTING-LH	Distorted	3,069.00 FS	*2,455.20 FS
2	1		*WING MIRROR CAP-LH	Missing	348.00 FS	*278.00 FS
3	1		*WING MIRROR GLASS-LH	Missing	1,298.00 FS	*1,038.40 FS
4	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
5	1		*SIDE MIRROR SUNDRY PARTS SET Supplementary	Cracked	127.00 FS	*101.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,892.00	3,873.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	280.00	280.00
2	TO RESPRAY LHS WING MIRROR COVER	New	500.00	180.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			972.00	652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >