

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000791/ATY3E2

Date: 27/06/2022

REFERENCE

Insured/Claimant:	WONG CHIN WAH	Policy No:	1900179022		
Date of Loss:	17/01/2022	Nature of Claim:	OD	Claim No:	8702403643SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFU5183R		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZD886423
Reg. Date:	31/10/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF3XL1013109
Colour:	White	Odometer:	39301 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,884.00	13,778.08	20,105.92	59.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,772.00	6,222.00	6,550.00	51.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,656.00	20,000.08	26,655.92	57.13
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	46,256.00	19,600.08	26,655.92	57.63
+ GST 7.00/7.00% (S\$)	3,237.92	1,372.01	1,865.91	57.63
Nett Amount (S\$)	49,493.92	20,972.09	28,521.83	57.63

INSPECTION

Date of Assignment:	24/01/2022		
Date Inspected:	21/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,308.00 FS	*858.40 FS
2	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	132.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	242.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE LOWER COVER	Not Necessary	58.00 FS	*- FS
5	2		*FRONT BUMPER GRILLE - LH / RH	Not Necessary	248.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	426.00 FS	*- FS
8	1		*FRONT BUMPER BRACKET	Not Necessary	24.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,594.00 FS	*1,275.20 FS
11	1		*RADIATOR STRIKER PLATE	Cracked	271.00 FS	*216.80 FS
12	1		*RADIATOR GRILLE COVER CAP	Not Necessary	47.00 FS	*- FS
13	1		*RADIATOR BRACKET	Not Necessary	46.00 FS	*- FS
14	1		*RADIATOR SECURING PLATE	Not Necessary	37.00 FS	*- FS
15	1		*FRONT CAMERA	Not Necessary	1,261.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
17	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	974.00 FS	*778.80 FS
18	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
19	1		*FRONT BUMPER TOP COVER	Deformed	137.00 FS	*109.60 FS
20	1		*AIR COND STRIKER	Necessary	9.00 FS	*6.64 FS
21	1		*CAUTION STICKER	Torn	16.00 FS	*12.40 FS
22	2		*HORN - LH / RH	Not Necessary	298.00 FS	*- FS
23	2		*HORN BRACKET - LH / RH	Not Necessary	50.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
25	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
26	1		*SET FRONT BUMPER WIRING	Not Necessary	750.00 FS	*- FS
27	1		*BONNET	Dented	3,695.00 FS	*2,956.00 FS
28	2		*BONNET HINGE - LH / RH	Not Necessary	162.00 FS	*- FS
29	1		*BONNET ATTACHMENT PARTS	Not Necessary	309.00 FS	*- FS
30	2		*BONNET STRIKER - LH / RH	Not Necessary	246.00 FS	*- FS
31	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	31.00 FS	*24.24 FS
32	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
33	2		*BONNET SWITCH - LH / RH	Not Necessary	455.00 FS	*- FS
34	1		*BONNET RELEASE ELEMENT	Not Necessary	65.00 FS	*- FS
35	1		*BONNET RELEASE LEVER	Not Necessary	16.00 FS	*- FS
36	1		*BONNET LOCK COVER	Not Necessary	11.00 FS	*- FS
37	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
38	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	264.00 FS	*210.40 FS
39	2		*HEADLIGHT - LH / RH	N/S Cracked	11,904.00 FS	*4,761.60 FS
40	2		*LIFT CYLINDER - LH / RH	Not Necessary	462.00 FS	*- FS
41	1		*LIFT CYLINDER HOSE	Torn	92.00 FS	*73.44 FS
42	1		*LOCK CARRIER	Cracked	1,412.00 FS	*1,129.60 FS
43	1		*A/C CONDENSER	Dented	569.00 FS	*454.80 FS
44	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	9.00 FS	*- FS
45	1		*ADDITIONAL RADIATOR	Not Necessary	982.00 FS	*- FS
46	1		*RADIATOR	Not Necessary	1,090.00 FS	*- FS
47	2		*RADIATOR RUBBER BUSH - UPPER	Not Necessary	90.00 FS	*- FS
48	2		*RADIATOR BUSH - LOWER	Not Necessary	22.00 FS	*- FS
49	6		*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
50	2		*RADIATOR AIR GUIDE - LH / RH	Torn	86.00 FS	*68.16 FS
51	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Torn	96.00 FS	*37.84 FS
52	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	520.00 FS	*- FS
53	1		*FRONT WHEEL HOUSING LINER - ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
54	2		*FRONT WHEEL HOUSING LINER COVER - LH / RH	Not Necessary	36.00 FS	*- FS
55	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	566.00 FS	*452.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
57	1		*SUNDRIES	Necessary	350.00 FS	*20.08 FS
58	1		*INTAKE AIR GUIDE (Supplementary)	Cracked	59.00 F	*46.48 F
F=Franchise part. S=SpcNett.						
				Total Parts (\$\$)	33,884.00	13,778.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO DISMANTLE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER	New	4,000.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,772.00	6,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >