

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000808/UGA3Q2**Date:** 17/06/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100027972-14
Claimant Vehicle No :	SMK3563K	Insured Vehicle No :	SGU6201D
Date of Loss:	23/01/2022	Nature of Claim:	TP
		Claim No:	8368776917SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3563K	Engine No:	L15B6001782
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82001459
Reg. Date:	05/04/2019 (Man. Year: 2019)	Odometer:	64945 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,329.08	5,266.08	3,063.00	36.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	2,530.00	1,680.00	39.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,539.08	7,796.08	4,743.00	37.83
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	12,539.08	6,200.00	6,339.08	50.55
+ GST 7.00/7.00% (S\$)	877.74	434.00	443.74	50.55
Nett Amount (S\$)	13,416.82	6,634.00	6,782.82	50.55
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,278.00		

INSPECTION

Date of Assignment:	24/01/2022	
Date Inspected:	24/01/2022	Inspected At: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,150.60 FL	*953.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	45.60 FL	*45.00 FL
3	1		*REAR BUMPER TOW COVER	Deformed	18.80 FL	*18.80 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	90.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR COVER	O/S Twisted	90.00 FL	*45.00 FL
6	2		*REAR BUMPER BRACKET	Not Necessary	47.00 FL	*- FL
7	1		*TAILGATE ASSY	Badly Dented	1,193.00 FL	*1,193.00 FL
8	1		*TAILGATE LOCK	Bent	256.00 FL	*186.90 FL
9	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	383.00 FL	*- FL
10	1		*TAILGATE REFLECTOR	O/S Cracked	790.00 FL	*395.00 FL
11	1		*TAILGATE LOGO	Not Necessary	38.00 FL	*- FL
12	1		*TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
13	1		*TAILGATE INNER TRIM BOARD	Torn	220.00 FL	*220.00 FL
14	1		*TAILGATE KEYLESS SWITCH ANTENNA	Not Necessary	58.00 FL	*- FL
15	2		*TAILGATE HINGE	Not Necessary	100.00 FL	*- FL
16	2		*TAILGATE DAMPER	Not Necessary	330.00 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Twisted	168.50 FL	*168.50 FL
18	1		*TAILLAMP	O/S Cracked	1,041.00 FL	*520.50 FL
19	4		*TAILLAMP CLIPS	Not Necessary	20.00 FL	*- FL
20	1		*REAR END PANEL	Badly Dented	601.50 FL	*560.20 FL
21	1		*REAR END PANEL TOP GARNISH	Distorted	155.50 FL	*155.50 FL
22	1		*REAR END PANEL BUZZER	No such part	85.50 FL	*- FL
23	1		*FLOOR PANEL	Crumpled	1,180.00 FL	*981.10 FL
24	1		*FLOOR WOODEN BOARD	Serviceable	585.00 FL	*- FL
25	1		*TOOLS COMPARTMENT	Distorted	285.00 FL	*285.00 FL
26	1		*REAR FENDER INNER TRIM BOARD (O/S)	Distorted	489.60 FL	*394.10 FL
27	2		*REAR WINDSCREEN MOULDING	Necessary	56.00 FL	*56.00 FL
28	2		*REAR WINDSCREEN MOULDING -TOP	No such part	113.00 FS	*- FS
29	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
30	1		*REAR WINDSCREEN PRIMER	Necessary	50.00 FS	*40.00 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
32	1		*INSULATION PADDING	Not Necessary	180.00 FS	*- FS
33	1		*SET PARKING SENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,235.60	6,512.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,906.52	1,246.52
Total Parts (\$\$)	8,329.08	5,266.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE UPHOLSTERY	New	200.00	80.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	300.00	90.00
3	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	350.00	0.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	100.00	50.00
5	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	30.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,500.00	1,100.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			4,210.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >