

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22000813/VTF3E2

Date: 13/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959995		
Claimant Vehicle No :	SLN5604J	Insured Vehicle No :	SLJ3084T		
Date of Loss:	19/01/2022	Nature of Claim:	TP	Claim No:	268526

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN5604J	Engine No:	3A92UDP5318
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH004053
Reg. Date:	09/05/2017 (Man. Year: 2016)	Odometer:	265190 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,631.79	4,292.15	20,339.64	82.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,030.00	2,630.00	3,400.00	56.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,661.79	6,922.15	23,739.64	77.42
Approved Total (Overridden) (S\$)		5,550.00		
Nett Amount (S\$)	30,661.79	5,550.00	25,111.79	81.90

INSPECTION

Date of Assignment:	24/01/2022	PROVI AUTOWORKS PTE LTD (HQ)
Date Inspected:	24/01/2022 Inspected At:	8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit
Estimated Period of Repair:	7.0 days	Singapore 415875

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Feb 2022)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN5604J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	878.00 FL	*791.00 FL
2	1		*BOOT LID LOGO	Necessary	89.00 FL	*69.00 FL
3	1		*BOOTLID EMBLEM (ATTRAGE)	Necessary	87.60 FL	*35.30 FL
4	1		*BOOTLID EMBLEM (C & C)	Necessary	85.40 FL	*60.00 FL
5	1		*BOOTLID OUTER CHROME MOULDING	Serviceable	317.80 FL	*- FL
6	1		*BOOTLID CAR PLATE LAMP (2PCS)	Cracked (1Pc Only)	98.00 FL	*49.00 FL
7	1		*BOOTLID INNER LOCK	Jammed	379.30 FL	*139.00 FL
8	1		*BOOTLID LOCK CATCH	Repair	35.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Cut	198.10 FL	*155.00 FL
10	2		*BOOTLID HINGE	Serviceable	422.00 FL	*- FL
11	1		*BOOTLID DECTECTOR SENSOR	Cut	312.00 FL	*150.00 FL
12	1		*BOOTLID DECTECTOR WIREHARNES	Cut	358.00 FL	*- FL
13	1		*BOOT LID OPENNER SWITCH	Serviceable	142.00 FL	*- FL
14	2		*TAILLAMP	Cracked	956.00 FL	*664.00 FL
15	2		*TAILLAMP PANEL	Dented	502.00 FL	*314.00 FL
16	1		*REAR BUMPER	Dented	708.00 FL	*708.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	178.20 FL	*178.20 FL
18	2		*REAR BUMPER ATTACHMENT RETAINER	Not Necessary	152.60 FL	*- FL
19	2		*REAR BUMPER SIDE AIR GUARD	Cut	234.00 FL	*98.00 FL
20	2		*REAR FENDER	Repair	1,780.00 FL	*- FL
21	2		*REAR FENDER SIDE EXTENTION PANEL	Serviceable	524.00 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Not Necessary	630.00 FL	*- FL
23	2		*REAR FENDER INNER SHIELD	Serviceable	192.00 FL	*- FL
24	2		*REAR CHASSIS FRAME MEMBER	Not Necessary	1,388.00 FL	*- FL
25	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FL	*- FL
26	1		*REAR END PANEL	Dented	462.00 FL	*462.00 FL
27	1		*REAR END PANEL TOP GARNISH	Distorted	210.00 FL	*210.00 FL
28	2		*REAR END PANEL AIR VENT	Cut	108.00 FL	*136.00 FL
29	1		*REAR END PANEL AIR VENT COVER	Cut	144.50 FL	*- FL
30	1		*REAR FLOOR PANEL	Repair	926.00 FL	*- FL
31	1		*REAR FLOOR PANEL LOWER MEMBER	Repair	421.00 FL	*- FL
32	2		*REAR FLOOR SIDE EXTENTION PANEL	Repair	508.00 FL	*- FL
33	1		*REAR FLOOR PANEL TOP BOARD	Cut	375.30 FL	*195.00 FL
34	1		*SPARE TYRE WHEEL NUT	Repair	112.00 FL	*- FL
35	1		*REAR EXHAUST PIPE BOX	Repair	591.00 FL	*- FL
36	2		*REAR EXHAUST MOULTING	Serviceable	76.00 FL	*- FL
37	1		*REAR EXHAUST INSULATOR	Serviceable	114.50 FL	*- FL
38	2		*SIDE SKIRT	Not Necessary	1,752.00 FL	*- FL
39	2		*REAR DOOR	Not Necessary	2,018.00 FL	*- FL
40	4		*REAR DOOR FRAME SIDE BLACK STICKER	Not Necessary	180.00 FL	*- FL
41	2		*REAR DOOR OUTER MOULDING	Not Necessary	396.00 FL	*- FL
42	2		*REAR DOOR INNER LOCK	Not Necessary	933.80 FL	*- FL
43	2		*REAR DOOR LOCK CATCH	Not Necessary	112.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	2		*REAR DOOR WEATHERSTRIP	Not Necessary	396.00 FL	*- FL
45	2		*FRONT SEAT BELT	Not Necessary	1,908.00 FL	*- FL
46	1		*SRS AIRBAG CONTOR UNIT	Not Necessary	1,542.00 FL	*- FL
47	1		*BOOTLID SEALANT	Not Necessary	878.00 FS	*- FS
48	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
49	1		*TAIL LAMP CLIP	Necessary	30.00 FS	*15.00 FS
50	2		*TAILLAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
51	2		*REAR FENDER SEALANT	Not Necessary	160.00 FS	*- FS
52	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
			}			
53	1		*REAR FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*- FS
			}			
54	2		*REAR FENDER EXTENTION PANEL SEALANT	Not Necessary	120.00 FS	*- FS
55	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
57	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*15.00 FS
58	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
59	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
60	2		*REAR CHASSIS FRAME SEALANT	Not Necessary	160.00 FS	*- FS
61	1		*SIDE SKIRT CLIP	Not Necessary	60.00 FS	*- FS
62	1		*REVERSE SENSOR	Cut	350.00 FS	*200.00 FS
63	1		*REVERSE CAMERA	Serviceable	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,031.10	4,733.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,399.31	441.35
Total Parts (\$\$)	24,631.79	4,292.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,000.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,200.00
3	REMOVE AND REFIX CUSHION SEAT AND INTERIOR TO FACILITATE REPAIR	New	400.00	60.00
4	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	30.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	30.00
6	REMOVE AND INSTALL REAR DOOR PART	New	180.00	0.00
7	REMOVE AND INSTALL REAR WINDSCREEN	New	250.00	0.00
8	REMOVE AND INSTALL REAR EXHAUST	New	200.00	80.00
9	TRANFER BOOTLID MECHANISM	New	150.00	30.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	SRS AIRBAG SYSTEM PROGRAMMING	New	650.00	0.00
Gross Labour Cost (\$\$)			6,030.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >