

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22000816/Vty3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	11/02/2022		
	ATTN: HO WINNIE			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 7221Y	Veh. Inspected	t	PA 6854T	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S2M03RQK	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		24/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	JTFHT02P300002577	Colour		SILVER	
	Odometer	697193 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	YOKOHAMA		6 mm	
	L/H Front Tyre	195 R15C	YOKOHAMA		6 mm	
	R/H Rear Tyre	195 R15C	YOKOHAMA		6 mm	
	L/H Rear Tyre	195 R15C	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	21/01/2022	Inspect Date /	Time	24/01/2022 (05:00 PM)	
_	Survey held at	rvey held at GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM22000816/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser