

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCK 101Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DENTED	1,928.00	1,928.00
2	FRONT BUMPER SIDE HOLDER @\$98.00 (CONSISTENT)	NOT NECESSARY	196.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	225.00	-
1	FRONT BUMPER SIDE CHROME MOULDING LH (CONSISTENT)	NOT NECESSARY	145.00	-
1	FRONT BUMPER SIDE GRILLE LH (CONSISTENT)	CRACKED	125.00	125.00
1	FRONT BUMPER SIDE LAMP LH (CONSISTENT)	CRACKED	289.00	289.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	686.00	-
1	FRONT BUMPER NOZZLE PUMP LH (CONSISTENT)	CRACKED	298.00	298.00
1	FRONT BUMPER SENSOR (CONSISTENT)	NOT NECESSARY	358.00	-
1	HEADLAMP LH (CONSISTENT)	NOT NECESSARY	4,366.00	-
1	RADIATOR COWLING LH (CONSISTENT)	NOT NECESSARY	158.00	-
	LESS 10% DISCOUNT		-	-264.00
			8,774.00	2,376.00
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		500.00	250.00
	SPRAY PAINTING.		500.00	250.00
	WIRING.		50.00	30.00
	TO REMOVE FRONT BUMPER SENSOR.		120.00	60.00
			1,170.00	590.00
	GRAND TOTAL		9,994.00	3,016.00

RECOMMENDED COST OF LUMP SUM REPAIRS		2,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM22000818/Avy3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.