

TPAXA.
Version.

SCK101Z 2013 August.

BMW 640i Gran Coupe.

WBA6A0204PZ11913.

Front Bumper Dented	1928	✓
Front Bumper Clips. New	50(SN)	✓
Front Bumper Side Holder x 02 ^{NP} _{new}	98 x 2 = 196	X.
Front Bumper Sponge ^{NP} _{new}	225	X.
Front Bumper Side Chrome Moulding LH. ^{NP} _{new}	145	X
Front Bumper Side Grille LH	Cracked 125	✓
Front Bumper Side Lamp LH	Cracked 289	✓
Front Bumper Reinforcement. ^{NP} _{new}	686	X
Front Bumper Nozzle Pump LH. Cracked	298	✓
Front Bumper Sensor ^{NP} _{new}	358	X.
Headlamp. LH. ^{NP} _{new}	4366	X.
Radiator Cooling LH. ^{NP} _{new}	158	X.
	2640	S.N: 30
	2376	

SCK1017.

Panel Beating

~~500~~ 250

Spry Painting. 590

~~500~~ 250

Wiring

~~50~~ 30

To remove front bumper sensor

~~120~~ 60

total: 3016

L/S: 2.4K

02 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: