



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7140C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH HEADLAMP ASSY	SCRATCHED	655.80	655.80
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	615.90	-
10	FRONT BUMPER CLIP	NECESSARY	55.00	55.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	160.40	160.40
1	LH FRONT DOOR ASSY	TO REPAIR SEE LABOUR	1,859.20	-
1	LH FRONT DOOR STEP BOARD	SERVICEABLE	146.80	-
	LESS 25% DISCOUNT		-873.28	-217.80
			2,619.82	653.40
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE AFFECTED PARTS/AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER AND LH FRONT DOOR ASSY.		500.00	400.00
	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS/AREAS.		600.00	400.00
	TO CHECK WIRING.		40.00	20.00
	TO RE-APPLY ANTI-RUST UNDERCOAT.		90.00	40.00
			1,230.00	860.00
GRAND TOTAL			3,849.82	1,513.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/AGI22000825/Vvf3n2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.