



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 2911Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	SCRATCHED	170.00	170.00
1	FRONT FORK LH	* CHECK	190.00	-
1	FRONT FORK RH	* CHECK	190.00	-
1	FRONT FAIRING	CRACKED	380.00	380.00
1	FRONT CENTRE FAIRING	CRACKED	220.00	220.00
1	FRONT INNER FAIRING LH	NOT NECESSARY	350.00	-
1	FRONT INNER FAIRING RH	CRACKED	350.00	350.00
1	FRONT HEADLAMP	CRACKED	480.00	480.00
1	FRONT HEADLAMP BRACKET	* CHECK	110.00	-
1	FRONT HANDLE BAR	BENT	180.00	180.00
1	FRONT SPEEDOMETER	CRACKED	900.00	900.00
1	FRONT TOP FAIRING	CRACKED	120.00	120.00
1	FRONT SIDE FAIRING LH	CRACKED	360.00	360.00
1	FRONT SIDE FAIRING RH	CRACKED	360.00	360.00
1	FRONT SIDE FAIRING LAMP LH	CRACKED	150.00	150.00
1	FRONT SIDE FAIRING LAMP RH	SCRATCHED	150.00	150.00
1	FRONT LOWER COVER	NOT NECESSARY	155.00	-
1	FRONT SIDE LOWER FAIRING LH	NOT NECESSARY	220.00	-
1	FRONT SIDE LOWER FAIRING RH	NOT NECESSARY	220.00	-
1	FRONT FOOT BRAKE RH	SCRATCHED	95.00	95.00
1	FRONT SIDE MIRROR LH	MISSING	80.00	80.00
1	REAR EXHAUST PIPE	BENT	1,200.00	1,200.00
1	CHASSIS FRAME (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-663.00	-519.50
			5,967.00	4,675.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NECESSARY	30.00	10.00
1	REAR BOX (SN)	SCRATCHED	280.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CENTRE BASKET (SN)	CRACKED	80.00	60.00
			390.00	220.00
	LABOUR			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	20.00
	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	220.00	-
	TO CONDUCT COMPUTER WHEEL ALIGNMENT.		80.00	40.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF CHASSIS FRAME.		480.00	350.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		350.00	250.00
			1,160.00	660.00
GRAND TOTAL			7,517.00	5,555.50
RECOMMENDED COST OF REPAIRS (EXCLUDE CHECK ITEMS S\$441.00 NETT)				5,555.50

Report Ref No. CS/AGI22000826/Rvf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.