

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 5722J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N)(CONSISTENT)	CRACKED	1,990.00	1,620.00
1	REAR BUMPER PAD (N)(CONSISTENT)	DEFORMED	480.00	480.00
1	REAR BUMPER SPONGE (N)(CONSISTENT)	SERVICEABLE	391.00	-
2	REAR BUMPER BRACKET @\$198.00 (N)(CONSISTENT)	NOT NECESSARY	396.00	-
1	REAR BUMPER CHROME (N)(CONSISTENT)	SERVICEABLE	499.00	-
1	REAR BUMPER SIDE CHROME (N)(CONSISTENT)	DEFORMED	620.00	310.00
2	REAR BUMPER SIDE HOLDER @\$210.00 (N) (CONSISTENT)	SERVICEABLE	420.00	-
1	REAR END PANEL (N)(CONSISTENT)	TO REPAIR SEE LABOUR	989.00	-
1	REAR END PANEL INNER GARNISH (N)(CONSISTENT)	NOT NECESSARY	388.00	-
	LESS 10% DISCOUNT		-	-241.00
			6,173.00	2,169.00
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIPS @\$6.00 (SN)(CONSISTENT)	NECESSARY	60.00	20.00
			60.00	20.00
	LABOUR			
	TO CHECK WIRING & REMOVE REFIT ALL WIRING AT ALL ACCIDENT AFFECTED AREA.	NOT NECESSARY	180.00	-
	TO KNOCKING,WELDING ,STRAIGHTENING REPAIR & RENEW ALL ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	400.00
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA & INNER PARTS.		1,000.00	400.00
	TO RUST PROOF ON ALL ACCIDENT AFFECTED AREA.		180.00	40.00
			2,260.00	840.00
	GRAND TOTAL		8,493.00	3,029.00



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22000829/Dea3q2



**Automotive Assessor / Investigator**