

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000831/BNY3Q2
Date: 17/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00010982100
Claimant Vehicle No :	GBE9024Y	Insured Vehicle No :	GBL2212E
Date of Loss:	20/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200544/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9024Y	Engine No:	YD25389991A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0006087
Reg. Date:	21/04/2016 (Man. Year: 2015)	Odometer:	164840 km
Colour:	Silver		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Windforce 5 mm	Rear Left Side:	Windforce 5 mm
Front Right Side:	Windforce 5 mm	Rear Right Side:	Windforce 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,867.55	29,185.21	12,682.34	30.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,740.00	6,930.00	3,810.00	35.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,607.55	36,115.21	16,492.34	31.35
Approved Total (Overridden) (S\$)		14,800.00		
	(S\$)	52,607.55	14,800.00	37,807.55
	+ GST 7.00/7.00% (S\$)	3,682.53	1,036.00	2,646.53
	Nett Amount (S\$)	56,290.08	15,836.00	40,454.08

INSPECTION

Date of Assignment:	19/09/2022	
Date Inspected:	09/02/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	24.0 days	

Adjuster: Lim Teow Guan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Nov 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9024Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	1,190.30 FL	*991.00 FL
2	1		*FRONT WINDSCREEN RUBBER MOULDING	Necessary	183.00 FL	*130.00 FL
3	1		*FRONT WINDSCREEN GLASS RH WIPER ARM	Not Damaged	116.40 FL	*- FL
4	1		*FRONT WINDSCREEN GLASS RH WIPER ARM BLADE	Not Damaged	32.00 FL	*- FL
5	1		*FRONT WINDSCREEN GLASS LH WIPER ARM	Not Damaged	116.40 FL	*- FL
6	1		*FRONT WINDSCREEN GLASS LH WIPER ARM BLADE	Not Necessary	32.00 FL	*- FL
7	1		*FRONT WINDSCREEN GLASS WIPER MOTOR	Scratched	435.60 FL	*352.00 FL
8	1		*FRONT WINDSCREEN GLASS WIPER MOTOR LINKAGE	Broken	232.60 FL	*184.50 FL
9	1		*FRONT WINDSCREEN GLASS WIPER GARNISH	Broken	451.20 FL	*123.50 FL
10	1		*FRONT WINDSCREEN GLASS WIPER GARNISH PANEL	Not Damaged	833.50 FL	*- FL
11	1		*FRONT PANEL	Dented	1,221.50 FL	*996.50 FL
12	1		*FRONT PANEL INSULATOR	No such part	64.00 FL	*- FL
13	1		*FRONT INNER RH PANEL	Dented	341.30 FL	*286.00 FL
14	1		*FRONT INNER CENTRE PANEL	Dented	472.00 FL	*300.00 FL
15	1		*FRONT INNER LH PANEL	Dented	386.80 FL	*286.00 FL
16	1		*FRONT RH CORNER PANEL	Dented	535.50 FL	*467.60 FL
17	1		*FRONT RH CORNER SIDE PANEL	Dented	155.40 FL	*155.40 FL
18	1		*FRONT LH CORNER PANEL	Dented	535.50 FL	*467.60 FL
19	1		*FRONT LH CORNER SIDE PANEL	Dented	155.40 FL	*155.40 FL
20	1		*FRONT BUMPER	Broken	571.90 FL	*541.40 FL
21	1		*FRONT BUMPER CENTRE GRILLE	Broken	940.00 FL	*760.00 FL
22	1		*FRONT BUMPER TOWING COVER	Missing	32.10 FL	*32.10 FL
23	1		*FRONT BUMPER RH FOG LAMP	Broken	311.80 FL	*215.20 FL
24	1		*FRONT BUMPER RH FOG LAMP COVER	Broken	114.20 FL	*105.10 FL
25	1		*FRONT BUMPER LH FOG LAMP	Broken	311.80 FL	*215.20 FL
26	1		*FRONT BUMPER LH FOG LAMP COVER	Broken	114.20 FL	*105.10 FL
27	1		*FRONT BUMPER REINFORCEMENT	Bent	630.20 FL	*345.40 FL
28	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	164.90 FL	*24.90 FL
29	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	164.90 FL	*24.90 FL
30	1		*FRONT BUMPER RH BRACKET	No such part	32.00 FL	*- FL
31	1		*FRONT BUMPER LH BRACKET	No such part	32.00 FL	*- FL
32	1		*FRONT BUMPER INNER BAR	Bent	235.00 FL	*224.00 FL
33	1		*FRONT BUMPER ARMATURE ASSY	No such part	705.00 FL	*- FL
34	1		*FRONT BUMPER RH STAY BRACKET	Bent	117.20 FL	*39.90 FL
35	1		*FRONT BUMPER LH STAY BRACKET	Bent	117.20 FL	*39.90 FL
36	1		*FRONT BUMPER LOWER AIR GUIDE	Broken	99.70 FL	*99.70 FL
37	1		*FRONT RH CHASSIS MEMBER EXTENSION PANEL	Dented	393.00 FL	*250.00 FL
38	1		*FRONT RH CHASSIS MEMBER EXTENSION PANEL SIDE SPLASH SHIELD	Dented	63.20 FL	*63.20 FL
39	1		*FRONT LH CHASSIS MEMBER EXTENSION PANEL	Broken	393.00 FL	*250.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT LH CHASSIS MEMBER EXTENSION PANEL SIDE SPLASH SHIELD	Dented	63.20 FL	*63.20 FL
41	1		*RH HEADLAMP ASSY	Broken	397.90 FL	*397.90 FL
42	1		*LH HEADLAMP ASSY	Broken	397.90 FL	*397.90 FL
43	1		*IPDM COVER	No such part	37.50 FL	*- FL
44	1		*HORN	Scratched	92.70 FL	*50.00 FL
45	1		*FRONT GRILLE	Broken	596.20 FL	*479.30 FL
46	1		*FRONT GRILLE EMBLEM	Necessary	79.90 FL	*42.80 FL
47	1		*TURBO INTERCOOLER	Dented	2,121.60 FL	*1,909.40 FL
48	1		*TURBO INTERCOOLER LOWER PIPE	Necessary	431.00 FL	*220.00 FL
49	1		*TURBO INTERCOOLER LOWER PIPE HOSE	Necessary	67.30 FL	*56.00 FL
50	2		*TURBO INTERCOOLER LOWER PIPE HOSE CLAMPS	Necessary	44.00 FL	*44.00 FL
51	1		*TURBO INTERCOOLER UPPER PIPE	Necessary	193.50 FL	*140.00 FL
52	1		*TURBO INTERCOOLER UPPER PIPE HOSE	Necessary	67.30 FL	*56.00 FL
53	2		*TURBO INTERCOOLER UPPER PIPE HOSE CLAMPS	Necessary	44.00 FL	*44.00 FL
54	1		*RADIATOR ASSY	Bent	716.60 FL	*716.60 FL
55	1		*RADIATOR FAN UPPER COWLING	Broken	135.80 FL	*48.00 FL
56	1		*RADIATOR FAN LOWER COWLING	Broken	14.00 FL	*14.00 FL
57	1		*RADIATOR FAN BLADE	Broken	169.00 FL	*93.20 FL
58	1		*RADIATOR LOWER SPLASH SHIELD	Broken	167.40 FL	*167.40 FL
59	1		*FRONT AIR DUCT	Broken	195.60 FL	*180.00 FL
60	1		*AIRCON HEATER ASSY	Broken	2,211.30 FL	*1,376.10 FL
61	1		*AIRCON HEATER PIPE	Dented	225.30 FL	*117.70 FL
62	1		*AIRCON HEATER HOSE	Dented	162.70 FL	*80.00 FL
63	1		*AIRCON BLOWER ASSY	Dented	714.60 FL	*219.50 FL
64	1		*THERMOSTAT SENSOR	Dented	261.60 FL	*150.00 FL
65	1		*AIRCON COOLING VALVE	Repeated	139.50 FL	*- FL
66	1		*AIRCON COOLING PIPE	Dented	171.20 FL	*117.00 FL
67	1		*AIRCON HIGH PRESSURE PIPE	Dented	235.60 FL	*117.70 FL
68	1		*AIRCON LOW PRESSURE PIPE	Dented	178.20 FL	*168.00 FL
69	1		*AIRCON RECEIVER DRIVE	Necessary	199.80 FL	*140.30 FL
70	1		*AIRCON RECEIVER DRIVE BRACKET	Necessary	49.50 FL	*49.50 FL
71	1		*POWER STEERING COOLING PIPE	Bent	289.80 FL	*135.00 FL
72	1		*AIR CLEANER BOX	Broken	453.10 FL	*276.90 FL
73	1		*AIR CLEANER BOX LOWER AIR DUCT	Necessary	495.60 FL	*367.20 FL
74	1		*AIR CLEANER BOX UPPER AIR DUCT	Necessary	242.20 FL	*59.90 FL
75	1		*FRONT RH DOOR	Dented	1,085.70 FL	*1,085.70 FL
76	1		*FRONT RH DOOR STEP GARNISH	Dented	117.70 FL	*117.70 FL
77	1		*FRONT RH DOOR UPPER HINGE	Bent	69.10 FL	*69.10 FL
78	1		*FRONT RH DOOR LOWER HINGE	Bent	69.10 FL	*69.10 FL
79	1		*FRONT LH DOOR	Dented	1,085.70 FL	*1,085.70 FL
80	1		*FRONT LH DOOR SIDE MIRROR	Missing	520.30 FL	*487.10 FL
81	1		*FRONT LH DOOR STEP GARNISH	Dented	117.70 FL	*117.70 FL
82	1		*FRONT LH DOOR STEP GARNISH INNER PANEL	Dented	128.60 FL	*128.60 FL
83	1		*FRONT LH DOOR UPPER HINGE	Bent	69.10 FL	*69.10 FL
84	1		*FRONT LH DOOR LOWER HINGE	Bent	69.10 FL	*69.10 FL
85	1		*FRONT LH DOOR CHECKER	Missing	88.20 FL	*88.20 FL
86	1		*FRONT LH DOOR OUTER PILLAR	Bent	931.00 FL	*693.00 FL
87	1		*FRONT LH DOOR INNER PILLAR	Bent	803.50 FL	*435.90 FL
88	1		*FRONT LH DOOR LOCK	Jammed	166.70 FL	*166.70 FL
89	1		*FRONT LH DOOR LOCK CATCH	Repeated	41.00 FL	*- FL
90	1		*FRONT LH DOOR GLASS REGULATOR GEAR	Bent	337.00 FL	*127.00 FL
91	1		*FRONT LH DOOR GLASS REGULATOR GEAR MOTOR	Scratched	269.00 FL	*269.00 FL
92	1		*FRONT LH DOOR INNER TRIM BOARD	Broken	481.70 FL	*330.00 FL
93	1		*FRONT LH DOOR OUTER UPPER MOULDING	Bent	195.00 FL	*157.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	1		*FRONT LH DOOR WEATHERSTRIP	Torn	106.30 FL	*106.30 FL
95	1		*FRONT LH DOOR ARCH RUBBER SEAL	Necessary	38.70 FL	*38.70 FL
96	1		*FRONT LH DOOR SPEAKER	Broken	155.90 FL	*60.00 FL
97	1		*FRONT LH DOOR GLASS CHANNEL RUBBER	Necessary	83.30 FL	*42.00 FL
98	1		*FRONT LH DOOR BACK PANEL	Dented	1,223.90 FL	*1,223.90 FL
99	1		*DASHBOARD	Not Damaged	1,103.90 FL	*- FL
100	1		*DASHBOARD ENFORCEMENT	Not Necessary	700.80 FL	*- FL
101	1		*STEERING AIRBAG	Activated	2,102.50 FL	*1,200.00 FL
102	1		*STEERING SPIRAL CLOCK SENSOR	Necessary	354.70 FL	*354.70 FL
103	1		*DRIVER SEAT BELT	Jammed	800.10 FL	*694.20 FL
104	1		*PASSENGER SEAT BELT	Jammed	800.10 FL	*694.20 FL
105	1		*AIRBAG CONTROL UNIT	Activated	873.80 FL	*741.20 FL
106	2		*AIRBAG SENSOR	Activated	378.20 FL	*280.00 FL
107	1		*BRAKE BOOSTER	Jammed	1,208.30 FL	*1,208.30 FL
108	1		*SET BRAKE PIPES	Necessary	393.10 FL	*393.10 FL
109	1		*BRAKE PIPE CONNECTOR	Necessary	62.90 FL	*62.90 FL
110	1		*FRONT WIRE HARNESS	Cut	1,133.90 FL	*990.00 FL
111	1		*LH FRONT WHEEL	Not Damaged	228.80 FL	*- FL
112	1		*LH FRONT WHEEL CAP	Not Damaged	151.20 FL	*- FL
113	1		*LH FRONT WHEEL BEARING	Jammed	155.50 FL	*130.00 FL
114	1		*LH FRONT WHEEL HUB	Dented	453.00 FL	*350.00 FL
115	1		*LH FRONT KNUCKLE ARM	Dented	452.10 FL	*351.50 FL
116	1		*LH FRONT SHOCK ABSORBER	Bent	177.30 FL	*125.00 FL
117	1		*LH FRONT UPPER ARM	Bent	331.00 FL	*219.50 FL
118	1		*LH FRONT LOWER ARM	Bent	220.40 FL	*220.40 FL
119	1		*LH FRONT LOWER ARM BALL JOINT	Dented	98.50 FL	*98.50 FL
120	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
121	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
122	1		*FRONT WINDSCREEN GLASS ERP BRACKET	Necessary	26.00 FS	*26.00 FS
123	1		*FRONT PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
124	1		*FRONT INNER RH PANEL JOINT SEALANT	Necessary	30.00 FS	*20.00 FS
125	1		*FRONT INNER CENTRE PANEL JOINT SEALANT	Necessary	45.00 FS	*20.00 FS
126	1		*FRONT INNER LH PANEL JOINT SEALANT	Necessary	30.00 FS	*20.00 FS
127	1		*FRONT RH CHASSIS MEMBER EXTENSION PANEL JOINT SEALANT	Necessary	45.00 FS	*30.00 FS
128	1		*FRONT RH CHASSIS MEMBER EXTENSION PANEL JOINT SEALANT	Necessary	45.00 FS	*30.00 FS
129	1		*FRONT LH DOOR OUTER PILLAR JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
130	1		*FRONT LH DOOR INNER PILLAR JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
131	1		*FRONT LH DOOR BACK PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
132	1		*FRONT LH DOOR COMPANY DETAIL STICKER	Necessary	35.00 FS	*20.00 FS
133	1		*FRONT RH DOOR COMPANY DETAIL STICKER	Necessary	35.00 FS	*20.00 FS
134	1		*BRAKE FLUID	Necessary	60.00 FS	*40.00 FS
135	1		*RADIATOR COOLANT	Necessary	70.00 FS	*40.00 FS
136	1		*FRONT NUMBER PLATE	Necessary	70.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	46,420.50	32,372.90
- List Item Discount on L Items 10.00/10.00% (\$)	4,552.95	3,187.69
Total Parts (\$)	41,867.55	29,185.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	3,600.00	3,000.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	2,200.00	1,800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	80.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	240.00	120.00
5	REMOVE AND REPLACE FRONT WINDSCREEN GLASS ,SEALANTS AND ERP BRACKET	New	200.00	120.00
6	REMOVE AND REPLACE AIRCON BLOWER ,AIRCON HEATER ,PIPES ,HOSES AND SENSORS TO ASSIST REPAIR .TO REFILL AIRCON GAS	New	380.00	200.00
7	REMOVE AND REPLACE RADIATOR ASSY ,HOSES ,PIPES AND FAN ASSY TO ASSIST REPAIR.TO REFILL COOLANT	New	280.00	80.00
8	REMOVE AND REPLACE DASHBOARD ,SPEAKER AND ALL DASHBOARD ATTACHMENTS PARTS TO ASSIST REPAIR	New	350.00	250.00
9	REMOVE AND REPLACE AIRBAG ,SENSORS ,SEAT BELT AND CONTROL UNIT TO ASSIST REPAIR	New	500.00	300.00
10	RESET ,ACTIVATE AND DIAGNOSE CONTROL UNIT AND FAULT CODES	New	450.00	120.00
11	REMOVE AND REPLACE BRAKE BOOSTER ,BRAKE MASTER PUMP,BRAKE PIPES ,BRAKE CONNECTORS AND SENSORS TO ASSIST REPAIR .TO BLAEEED BRAKE SYSTEM AND CHECK FOR FUNCTIONAL	New	320.00	200.00
12	REMOVE AND REINSTALL STEERING WHEEL ,STEERING COUPLING,STEERING SHAFT ,STEERING BRACKET AND SENSORS TO ASSIST REPAIR	New	300.00	120.00
13	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH TO REPAIR BOTH FRONT CHASSIS FRAMES	New	550.00	200.00
14	REMOVE AND REPLACE TURBO INTERCOOLER INTERCOOLER PIPES,INTERCOOLER HOSES AND SENSORS TO ASSIST REPAIR	New	300.00	80.00
15	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	350.00	80.00
16	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
17	REMOVE AND REINNSTALL LH FRONT DOOR BACK PANEL INNER TRIM ,CARPET ,SEATS AND BOARDS TO ASSIST REPAIR	New	380.00	100.00
18	REMOVE AND REPLACE LH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	120.00	80.00
Gross Labour Cost (\$\$)			10,740.00	6,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >