

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000841/ETY3N2**Date:** 23/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00118072103	
<b>Claimant Vehicle No :</b>	GBH6062R	<b>Insured Vehicle No :</b>	SGJ2594D	
Date of Loss:	21/01/2022	Nature of Claim:	TP	Claim No: SNM22D200541/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH6062R</b>		Engine No:	K9KE628D417752
Make & Model:	NISSAN NV200, 1.5 (A)		Chassis No:	VSKYBAM20Z0156620
Reg. Date:	25/07/2018 (Man. Year: 2017)		Odometer:	166789 km
Colour:	Silver			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,357.51	2,704.37	653.14	19.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,590.00	480.00	23.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,427.51</b>	<b>4,294.37</b>	<b>1,133.14</b>	<b>20.88</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,450.00</b>		
<b>(\$\$)</b>	5,427.51	3,450.00	1,977.51	36.43
<b>+ GST 7.00/7.00% (\$\$)</b>	379.93	241.50	138.43	36.44
<b>Nett Amount (\$\$)</b>	<b>5,807.44</b>	<b>3,691.50</b>	<b>2,115.94</b>	<b>36.43</b>

**INSPECTION**

Date of Assignment:	15/02/2022	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Date Inspected:	28/02/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Jun 2022)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH6062R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	485.90 FN	*485.90 FN
2	1		*REAR BUMPER RETAINER LH	Broken	37.20 FN	*37.20 FN
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	61.90 FN	*- FN
4	1		*REAR BUMPER SPONGE	Broken	94.00 FN	*94.00 FN
5	1		*REAR BACK DOOR LH	Dented	1,336.00 FN	*1,336.00 FN
6	1		*REAR BACK DOOR HINGE BOTTOM LH	Bent	104.00 FN	*104.00 FN
7	1		*REAR BACK DOOR LWR SEAL LH	Not Necessary	88.40 FN	*- FN
8	1		*REAR BACK DOOR WEATHERSTRIP	Not Necessary	111.60 FN	*- FN
9	1		*REAR BACK DOOR INNER TRIM LH	Not Necessary	213.00 FN	*- FN
10	10		*REAR BACK DOOR INNER TRIM CLIPS	Not Necessary	44.00 FN	*- FN
11	1		*REAR END PANEL	Dented	174.10 FN	*174.10 FN
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	83.30 FN	*- FN
13	1		*REAR TAILLAMP LH	Broken	277.20 FN	*277.20 FN
14	1		*REAR BACK DOOR NV200 LOGO	Necessary	94.40 FN	*76.00 FN
15	1		*REAR BACK DOOR EMBLEM	Necessary	64.90 FN	*64.90 FN
16	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
17	1		*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
18	1		*REAR NUMBER PLATE	Cut	35.00 FS	*35.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*35.00 FS
20	10		*REAR BUMPER CLIPS	Necessary	39.60 FS	*30.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,684.50</b>	<b>2,969.30</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	326.99	264.93
<b>Total Parts (\$\$)</b>	<b>3,357.51</b>	<b>2,704.37</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK REAR FENDER LH,WELD,REMOVE & REPLACE ABOVE PARTS	New	1,000.00	800.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	700.00	600.00
3	TO REMOVE & REFIX RR DOOR GLASS LH	New	80.00	80.00
4	TO CHECK WIRING	New	30.00	30.00
5	TO TRANSFER DOOR LH MECHANISM	New	60.00	50.00
6	TO RESET & CLEAR ENGINE FAULT CODE	New	200.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,070.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >