5/12/22, 9:53 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000859/EQY3N2

**Date:** 12/05/2022

**REFERENCE** 

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00156512100

Claimant Vehicle No :

SNB5345X

Insured Vehicle No :

GBL6163L

Date of Loss:

21/01/2022

Nature of Claim: TP

Claim

Odometer:

SNM22D200597/C02/LEWLC

4856 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SNB5345X

 Make & Model:
 MERCEDES-BENZ B180, 1.3 PROGRESSIVE (A)
 Engine No:
 28291480637233

 Reg. Date:
 27/08/2021 (Man. Year: 2021)
 Chassis No:
 W1K2470842J302790

Colour: Grey

Engine Capacity: 1332 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,783.68	6,400.92	382.76	5.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,300.00	6,740.00	1,560.00	18.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,083.68	13,140.92	1,942.76	12.88
+ GST 7.00/7.00% (S\$)	1,055.86	919.86	136.00	12.88
Nett Amount (S\$)	16,139.54	14,060.78	2,078.76	12.88

**INSPECTION** 

Date of Assignment: 25/01/2022

Cycle & Carriage Industries Pte Ltd (Pandan Loop)

Date Inspected: 08/02/2022 Inspected At: 188 Pandan Loop

Singapore 128378

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

#### **REPAIR DETAILS**

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 May 2022)

Parts: 144 MERCEDES-BENZ B180 1.3 PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNB5345X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SUPPORT PANEL	Broken	620.36 FS	*620.36 FS
2	1		*LEFT HEADLAMP UNIT	Broken	3,194.65 FS	*3,194.65 FS
3	1		*LEFT HEADLAMP CONTROL UNIT,COMPLETE	Shorted	509.35 FS	*509.35 FS
4	1		*LEFT FRONT FENDER	Dented	660.13 FS	*660.13 FS
5	1		*LEFT FRONT FENDER EDGE GUARD	Not Necessary	7.23 FS	*- FS
6	1		*LEFT FRONT FENDER LINER FF	Not Necessary	199.70 FS	*- FS
7	1		*LEFT FRONT FENDER LINER END PIECE	Not Necessary	25.01 FS	*- FS
8	1		*FRONT BUMPER	Broken	1,337.11 FS	*1,337.11 FS
9	1		*FRONT BUMPER MB EMBLEM	Broken	79.32 FS	*79.32 FS
10	1		*FRONT BASIC CARRIER FOR BUMPER	Not Necessary	150.82 FS	*-FS
F=Fra	nchise	part. S=SpcN	Nett.	=		
				Total Parts (S\$)	6,783.68	6,400.92

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	4,800.00	3,840.00
2	RESPRAY BONNET,LEFT FRONT FENDER AND FRONT BUMPER	New	3,000.00	2,400.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS,RESET SYSTEM TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
	Gross Lab	our Cost (S\$)	8,300.00	6,740.00
	Report was unsubmitted during the	nis print-out.		

< END OF ESTIMATES >