

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000861/AQY3E2

Date: 15/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00140942100
Claimant Vehicle No : SKV3027H **Insured Vehicle No :** SJJ5529M
Date of Loss: 22/01/2022 Nature of Claim: TP Claim No: SNM22D200612/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV3027H**
Make & Model: KIA CERATO FORTE, 2.0 L SX SR ABS D/AB 2WD (A) Engine No: G4KD9H518554
Reg. Date: 29/05/2009 (Man. Year: 2009) Chassis No: KNAFH222395059655
Colour: White Odometer: 267137 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,237.60	3,634.10	603.50	14.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	960.00	1,240.00	56.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,437.60	4,594.10	1,843.50	28.64
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	6,437.60	3,600.00	2,837.60	44.08

INSPECTION

Date of Assignment: 25/01/2022
Date Inspected: 25/01/2022 Inspected At: Unimotor Company - Kaki Bukit (HQ)
1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2022)

Parts: 143 KIA CERATO FORTE 2.0 L SX SR ABS D/AB 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV3027H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H DOOR ASSY	Dented	1,104.00 FL	*1,104.00 FL
2	2		*FRONT L/H DOOR HINGES	Not Necessary	116.00 FL	*- FL
3	1		*FRONT L/H DOOR LOCK	Damaged	353.00 FL	*298.00 FL
4	1		*FRONT L/H DOOR OUTER HANDLE	Cut	212.00 FL	*212.00 FL
5	1		*FRONT L/H DOOR WEATHERSTRIP	Not Necessary	226.00 FL	*- FL
6	1		*FRONT L/H DOOR INNER TRIM BOARD	Cracked	757.00 FL	*655.00 FL
7	1		*FRONT L/H DOOR TOP BLACK STICKER	Necessary	47.00 FL	*47.00 FL
8	1		*FRONT L/H DOOR CENTRE BLACK STICKER	Necessary	40.00 FL	*40.00 FL
9	1		*REAR L/H DOOR ASSY	Dented	984.00 FL	*984.00 FL
10	2		*REAR L/H DOOR HINGES	Not Necessary	116.00 FL	*- FL
11	1		*REAR L/H DOOR TOP BLACK STICKER	Necessary	47.00 FL	*47.00 FL
12	1		*REAR L/H DOOR CENTRE BLACK STICKER	Necessary	40.00 FL	*40.00 FL
13	1		*L/H CENTRE SILL PANEL OUTER SPOILER	Deformed	400.00 FS	*350.00 FS
14	1		*REAR L/H DOOR WEATHERSTRIPS	Cut	222.00 FL	*222.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,664.00	3,999.00
- List Item Discount on L Items 10.00/10.00% (S\$)	426.40	364.90
Total Parts (S\$)	4,237.60	3,634.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM / REWIRE DAMAGED PORTION	New	100.00	30.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,000.00	500.00
3	TO PUTTY AND RESPRAY DAMAGED PORTION	New	900.00	400.00
4	TO SRARY UNDERCOATING IN REPAIR	New	100.00	30.00
5	TO DISM / REFIX SEAT, PANEL LINING, ROOF LINING	New	100.00	0.00
Gross Labour Cost (\$)			2,200.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >