

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000864/DQY3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00009842101
Claimant Vehicle No :	SNB8785P	Insured Vehicle No :	SMM2465G
Date of Loss:	22/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200570/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB8785P		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK067325
Reg. Date:	04/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF59JA127858
Colour:	Grey	Odometer:	40826 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	83,634.98	20,840.30	62,794.68	75.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,300.00	2,280.00	9,020.00	79.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	94,934.98	23,120.30	71,814.68	75.65
Approved Total (Overridden) (\$\$)		18,000.00		
Nett Amount (\$\$)	94,934.98	18,000.00	76,934.98	81.04

INSPECTION

Date of Assignment:	28/02/2022	C.s.ong Auto Pte Ltd (HQ) 10, ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT SINGAPORE 568047 Singapore 568047
Date Inspected:	25/01/2022 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2022)

Parts: 143 AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB8785P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEAD LAMP LH /RH	O/S Mtg Broken / N/S Cracked	17,960.00 FL	*14,373.30 FL
2	2		*HEAD LAMP LOWER BRACKET LH /RH	Not Necessary	680.00 FL	*- FL
3	1		*BONNET	Not Necessary	3,531.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	589.20 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	941.00 FL	*- FL
6	1		*FRONT GRILLE	Cracked	1,441.90 FL	*1,355.20 FL
7	1		*FRONT GRILLE CHROME	Not Necessary	1,049.20 FL	*- FL
8	1		*FRONT GRILLE LOGO	Serviceable	189.00 FL	*- FL
9	1		*FRONT BUMPER	Deformed / Distorted	2,980.00 FL	*1,800.80 FL
10	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	420.00 FL	*- FL
11	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	120.00 FL	*- FL
12	2		*FRONT BUMPER FOG LAMP GARNISH LH RH	Not Necessary	1,560.20 FL	*- FL
13	2		*FRONT BUMPER FOG LAMP CHROME LH/RH	Not Necessary	548.00 FL	*- FL
14	1		*FRONT BUMPER SENSOR (4 PCS)	2 PCS Damaged/2PCSNotNecessary	1,400.00 FL	*390.24 FL
15	1		*SET FRONT BUMPER SENSOR HOLDER	Serviceable	100.00 FL	*- FL
16	1		*SET FRONT BUMPER SENSOR O-RING (2 PCS Not Necessary)	Necessary (2 PCS ONLY)	50.00 FL	*10.00 FL
17	1		*FRONT BUMPER SENSOR WIRE HARNESS	Not Necessary	3,740.00 FL	*- FL
18	1		*FRONT BUMPER UNDERCOVER	Not Necessary	410.00 FL	*- FL
19	1		*FRONT BUMPER SPONGE	Cracked	339.00 FL	*124.00 FL
20	1		*FRONT REINFORCEMENT BAR	Dented	1,498.00 FL	*845.00 FL
21	1		*FRONT SUPPORT PANEL	Not Necessary	2,190.40 FL	*- FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	384.00 FL	*- FL
23	1		*A/C CONDENSOR	Not Necessary	1,782.00 FL	*- FL
24	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	1,440.00 FL	*- FL
25	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	598.00 FL	*- FL
26	1		*RADIATOR ASSY	Not Necessary	2,195.41 FL	*- FL
27	1		*RADIATOR FAN COMPLETE	Not Necessary	1,599.00 FL	*- FL
28	2		*FRONT FENDER LH/RH	Not Necessary	3,578.00 FL	*- FL
29	2		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	858.00 FL	*- FL
30	1		*BOOTLID	Not Necessary	4,495.00 FL	*- FL
31	1		*BOOTLID LOGO	Not Necessary	120.00 FL	*- FL
32	1		*BOOTLID A5 EMBLEM	Not Necessary	149.00 FL	*- FL
33	1		*BOOTLID TSFI EMBLEM	Not Necessary	142.00 FL	*- FL
34	1		*BOOTLID TTTT EMBLEM	Not Necessary	155.00 FL	*- FL
35	2		*BOOTLID LAMP LH/RH	Not Necessary	2,182.00 FL	*- FL
36	1		*BOOTLID LOCK	Not Necessary	489.00 FL	*- FL
37	1		*BOOTLID INNER TRIM	Not Necessary	1,194.00 FL	*- FL
38	2		*BOOTLID HINGE LH/RH	Not Necessary	438.00 FL	*- FL
39	2		*TAIL LAMP LH/RH	Not Necessary	4,982.00 FL	*- FL
40	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	420.00 FL	*- FL
41	1		*REAR BUMPER	Distorted / Mtg Broken	2,689.00 FL	*2,003.20 FL
42	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	498.00 FL	*- FL
43	1		*REAR BUMPER CENTER CHROME MOULDING	Bent	981.00 FL	*812.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	482.00 FL	*- FL
45	1		*REAR BUMPER SENSOR (4 PCS)	2 PCS Damage/ 2 PCS Not Necessary	1,396.00 FL	*390.24 FL
46	1		*SET REAR BUMPER SENSOR HOLDER	Serviceable	100.00 FL	*- FL
47	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	3,856.00 FL	*- FL
48	1		*REAR BUMPER CENTER BRACKET	Not fitted	582.00 FL	*- FL
49	1		*REAR BUMPER SPONGE	Not fitted	399.00 FL	*- FL
50	1		*REAR REINFORCEMENT BAR	Dented	1,984.00 FL	*940.00 FL
51	1		*REAR END PANEL	Repair	2,851.00 FL	*- FL
52	1		*REAR END PANEL TOP GARNISH	Not Necessary	528.00 FL	*- FL
53	1		*REAR EXHAUST PIPE	Not Necessary	2,094.00 FL	*- FL
54	1		*REAR EXHAUST MOUNTING	Not Necessary	192.00 FL	*- FL
55	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	394.00 FL	*- FL
56	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	2,970.00 FL	*- FL
57	2		*REAR FENDER INNER SHIELD LH/RH	Not Necessary	850.00 FL	*- FL
58	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
61	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
62	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
63	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*COOLANT	Not Necessary	100.00 FS	*- FS
65	1		*BOOTLID LAMP CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
67	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
68	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
69	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
70	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
72	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*FRONT & REAR NO PLATE & GARNISH	1 PC Bent / 1 PC Not Necessary	200.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	92,813.31	23,144.78
- List Item Discount on L Items 10.00/10.00% (\$)	9,178.33	2,304.48
Total Parts (\$)	83,634.98	20,840.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,000.00	300.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,400.00	600.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,400.00	500.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	New	200.00	0.00
8	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
10	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
11	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
12	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	300.00	0.00
13	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	500.00	150.00
Gross Labour Cost (\$\$)			11,300.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >