

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22000871/UPA3Q2**Date:** 12/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SMY5776B **Insured Vehicle No :** GBK9007R

Date of Loss: 24/01/2022 Nature of Claim: TP Claim No: MFL2022D0000856

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY5776B**

Make & Model: TOYOTA LEXUS, 2.5 ES300H CVT (A) Engine No: 2AR1467233

Reg. Date: 25/06/2016 (Man. Year: 2016) Chassis No: JTHBW1GG502121982

Colour: Grey Odometer: 94690 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40Z R19 Rear Tyre Size: 255/40Z R19

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,333.01	7,529.40	5,803.61	43.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	900.00	1,640.00	64.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,873.01	8,429.40	7,443.61	46.89
Approved Total (Overridden) (S\$)		6,700.00		
Nett Amount (S\$)	15,873.01	6,700.00	9,173.01	57.79
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,007.45		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 25/01/2022

Date Inspected: 25/01/2022 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2022)

Parts: 143 TOYOTA LEXUS 2.5 ES300H CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY5776B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,160.30 F	*960.30 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Not Necessary	98.20 F	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*FRONT BUMPER PDC SENSOR O/S	Not Necessary	349.20 F	*- FL
5	1		*FRONT SUPPORT PANEL	Repair	745.21 F	*- FL
6	1		*HEADLAMP ASSY O/S	Cracked	6,921.50 F	*6,021.50 FL
7	1		*WIPER WASHER TANK	Serviceable	366.20 F	*- FL
8	1		*FRONT FENDER O/S	Dented	1,534.20 F	*1,334.20 FL
9	1		*BONNET	Repair	2,108.20 F	*- FL
					Sub Total (\$\$)	13,333.01 8,366.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 836.60
					Total Parts (\$\$)	13,333.01 7,529.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX FRONT PDC SENSOR	New	80.00	50.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	TO SPRAY RUST PROOFING	New	50.00	30.00
5	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	300.00
7	TO PUTTY & SPRAY PAINTING	New	1,180.00	500.00
Gross Labour Cost (\$\$)			2,540.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >