

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000873/APA3Q2**Date:** 25/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700010180
Claimant Vehicle No :	SLU7876R	Insured Vehicle No :	SLN1810G
Date of Loss:	20/01/2022	Nature of Claim:	TP
		Claim No:	2867015018SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7876R	Engine No:	1ZR1995893
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH604572188
Reg. Date:	14/12/2017 (Man. Year: 2017)	Odometer:	127447 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,242.35	12,782.70	14,459.65	53.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	4,360.00	1,590.00	26.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,192.35	17,142.70	16,049.65	48.35
Approved Total (Overridden) (S\$)		13,800.00		
(S\$)	33,192.35	13,800.00	19,392.35	58.42
+ GST 7.00/7.00% (S\$)	2,323.46	966.00	1,357.46	58.42
Nett Amount (S\$)	35,515.81	14,766.00	20,749.81	58.42
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,173.45		
Global Sum Settlement (S\$)		16,000.00		

INSPECTION

Date of Assignment:	21/01/2022	Ventures Auto Pte Ltd (HQ)
Date Inspected:	21/01/2022 Inspected At:	23 Kaki Bukit Avenue 4, #04-01, AAS Kaki Bukit Centre
Estimated Period of Repair:	12.0 days	Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$68,000.00(est) less LTA Rebate: \$37,867.00(est) = Nett Value
:\$30,133.00(est)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	623.10 FL	*568.00 FL
2	1		*REAR BUMPER SIDE RETAINERS	Not Necessary	105.70 FL	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
4	1		*TAILLAMP	Not Necessary	397.80 FL	*- FL
5	1		*TAILLAMPS INNER SEALER	Not Necessary	38.00 FL	*- FL
6	1		*SET TAILLAMPS CLIPS	Not Necessary	25.00 FL	*- FL
7	1		*REAR FENDER LH	Repair	1,568.60 FL	*- FL
8	1		*REAR FENDER INNER COWLING LH	Not Necessary	198.50 FL	*- FL
9	1		*REAR DOOR PILLAR FRAME LH	Repair	845.20 FL	*- FL
10	1		*REAR DOOR LH	Distorted	1,245.60 FL	*1,245.60 FL
11	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	285.90 FL	*- FL
12	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	1,245.60 FL	*- FL
13	1		*REAR DOOR GLASS REGULATOR LH	Damaged	325.60 FL	*325.60 FL
14	1		*REAR DOOR GLASS REGULATOR MOTOR LH	Not Necessary	568.40 FL	*- FL
15	1		*REAR DOOR INNER TRIM LH	Cracked	897.60 FL	*634.00 FL
16	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	145.10 FL	*- FL
17	2		*REAR DOOR BLACK STICKER LH	Necessary	130.40 FL	*90.00 FL
18	2		*REAR DOOR HINGES	Bent	178.00 FL	*178.00 FL
19	1		*REAR DOOR CHECKER LH	Not Necessary	121.40 FL	*- FL
20	1		*REAR DOOR QUARTER GLASS RUBBER LH	Not Necessary	148.60 FL	*- FL
21	1		*REAR DOOR WEATHERSTRIP LH DOOR	Cut	183.10 FL	*183.10 FL
22	1		*REAR DOOR WEATHERSTRIP LH FRAME	Not Necessary	189.60 FL	*- FL
23	1		*REAR RIM LH	Cut	671.70 FS	*450.00 FS
24	1		*FRONT BONNET LH	Not Necessary	1,058.90 FL	*- FL
25	1		*FRONT DOOR LH	Distorted	1,210.20 FL	*1,008.00 FL
26	1		*FRONT DOOR OUTER MOULDING LH	Deformed	161.40 FL	*161.40 FL
27	2		*FRONT DOOR BLACK STICKER LH	Necessary	166.60 FL	*90.00 FL
28	1		*FRONT DOOR WING MIRROR LH	Damaged	1,263.10 FL	*1,006.00 FL
29	1		*FRONT DOOR OUTER HANDLE	Damaged	285.90 FL	*285.90 FL
30	1		*FRONT DOOR OUTER HANDLE COVER	Damaged	48.60 FL	*48.60 FL
31	2		*FRONT DOOR HINGES	Bent	179.00 FL	*179.00 FL
32	1		*FRONT DOOR CHECKER LH	Damaged	121.40 FL	*121.40 FL
33	1		*FRONT DOOR INNER LOCK LH	Jammed	525.10 FL	*371.00 FL
34	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	58.10 FL	*- FL
35	1		*FRONT DOOR WEATHERSTRIP LH DOOR	Cut	189.60 FL	*189.60 FL
36	1		*FRONT DOOR WEATHERSTRIP LH FRAME	Not Necessary	195.50 FL	*- FL
37	1		*FRONT DOOR REGULATOR MOTOR LH	Not Necessary	568.40 FL	*- FL
38	1		*FRONT DOOR REGULATOR GEAR LH	Damaged	311.40 FL	*311.40 FL
39	1		*FRONT DOOR CHANNEL LH	Bent	178.10 FL	*178.10 FL
40	1		*FRONT DOOR CHANNEL SEAL LH	Not Necessary	69.10 FL	*- FL
41	2		*FRONT DOOR STOPPER LH	Not Necessary	56.60 FL	*- FL
42	1		*FRONT DOOR INNER TRIM LH	Cracked	897.50 FL	*625.00 FL
43	1		*SET FRONT DOOR INNER TRIM CLIPS	Necessary	40.00 FL	*30.00 FL
44	1		*FRONT DOOR SPEAKER LH	Cracked	187.50 FS	*120.00 FS
45	1		*FRONT DOOR WINDOW GLASS LH	Not Necessary	698.50 FL	*- FL
46	2		*FRONT DOOR STICKER LH	Repeated	139.60 FL	*- FL
47	1		*FRONT CENTRE PILLAR LH	Distorted	896.30 FL	*896.30 FL
48	1		*FRONT CENTRE PILLAR INNER TRIM LH (LOWER)	Deformed	345.20 FL	*345.20 FL
49	1		*SIDE ROCKER PANEL LH	Dented	856.90 FL	*856.90 FL
50	1		*FRONT BUMPER	Torn	592.50 FL	*592.50 FL
51	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	89.60 FL	*- FL
52	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
53	1		*HEADLAMPS	Not Necessary	2,845.30 FL	*- FL
54	1		*SET HEADLAMPS CLIPS	Not Necessary	30.00 FL	*- FL
55	1		*FRONT FENDER	Dented	731.80 FL	*656.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT INNER FENDER PANEL	Deformed	568.90 FL	*568.90 FL
57	1		*FRONT FENDERS INNER SHIELD	Deformed	198.60 FL	*198.60 FL
58	1		*FRONT FENDERS INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
59	1		*FRONT FENDER EMBLEM VVTI	Necessary	89.60 FL	*89.60 FL
60	1		*FRONT FENDERS OUTER GARNISH LH	Not Necessary	78.50 FL	*- FL
61	1		*FRONT FENDER INNER SUPPRESSOR GARNISH LH	Deformed	110.60 FL	*110.60 FL
62	1		*FRONT FENDERS INNER HOUSING LH	Repair	491.60 FL	*- FL
63	1		*FRONT RIM LH	Cut	671.70 FS	*450.00 FS
64	1		*FRONT SHOCK ABSORBER	Bent	526.90 FL	*438.00 FL
65	1		*FRONT LOWER ARM	Bent	518.90 FL	*518.90 FL
66	1		*FRONT KNUCKLE ARM	Damaged	498.60 FL	*498.60 FL
67	1		*FRONT WHEEL BEARING	Damaged	345.20 FL	*345.20 FL
68	1		*FRONT ANTI ROLL BAR	Not Necessary	253.10 FL	*- FL
69	2		*FRONT ANTI ROLL BAR BUSH	Not Necessary	72.00 FL	*- FL
70	1		*FRONT ANTI ROLL BAR LINK LH	Not Necessary	125.10 FL	*- FL
71	1		*FRONT DRIVE SHAFT LH	Not Necessary	1,210.10 FL	*- FL
72	1		*STEERING RACK AND PINION	Bent	1,328.60 FL	*1,328.60 FL
73	1		*STEERING CROSS MEMBER	Not Necessary	1,925.30 FL	*- FL
74	1		*SET DOOR VISOR	Necessary	250.00 FS	*160.00 FS
75	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
76	1		*SET REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
77	2		*FRONT SPORT RIM TYRE	Not Necessary	700.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,429.50	16,623.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,187.15	3,840.90
Total Parts (\$\$)	27,242.35	12,782.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	1,700.00
2	SPRAY PAINTING	New	2,200.00	1,800.00
3	CHECK WIRING ON HEADLAMP AND FOCUSING	New	120.00	0.00
4	ANTI RUST	New	200.00	150.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	150.00	120.00
6	TO TRANSFER FRONT DOOR MECHANISM	New	150.00	80.00
7	TO TRANSFER REAR DOOR MECHANISM	New	150.00	80.00
8	REMOVE AND INSTALL REVERSE SENSORS	New	120.00	50.00
9	REMOVE AND INSTALL REAR FUEL TANK	New	120.00	0.00
10	REMOVE AND INSTALL REAR WINDSCREEN	New	120.00	0.00
11	REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	300.00	300.00
12	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			5,950.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >