

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22000874/DTF3N2
Date: 14/06/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001861800
Claimant Vehicle No :	SKD2413C	Insured Vehicle No :	SMQ9554R
Date of Loss:	22/01/2022	Nature of Claim:	TP
		Claim No:	268736

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD2413C	Engine No:	CAV343727
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 L (A)	Chassis No:	WVWZZZ13ZCV011587
Reg. Date:	11/11/2011 (Man. Year: 2011)	Odometer:	162003 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35R19	Rear Tyre Size:	225/35R19
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,257.15	9,475.26	44,781.89	82.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,770.00	2,180.00	8,590.00	79.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	65,027.15	11,655.26	53,371.89	82.08
Approved Total (Overridden) (S\$)		9,300.00		
(S\$)	65,027.15	9,300.00	55,727.15	85.70
+ GST 7.00/7.00% (S\$)	4,551.90	651.00	3,900.90	85.70
Nett Amount (S\$)	69,579.05	9,951.00	59,628.05	85.70

INSPECTION

Date of Assignment:	25/01/2022	
Date Inspected:	25/01/2022	Inspected At: C. S. Ong Auto Pte Ltd (HQ) BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

FOR MANDATE ONLY

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2022)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD2413C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	3,784.00 FL	*1,199.55 FL
2	1		*BONNET LOGO	Necessary	132.00 FL	*86.70 FL
3	1		*BONNET LOCK	Serviceable	349.00 FL	*- FL
4	2		*BONNET HINGE LH/RH	Repair	256.00 FL	*- FL
5	1		*BONNET INNER TRIM	Not Necessary	849.00 FL	*- FL
6	2		*HEADLAMP LH/RH	Mounting Cracked/Broken	5,968.20 FL	*2,044.00 FL
7	2		*HEAD LAMP LOWER BRACKET LH/RH	No such part	578.00 FL	*- FL
8	1		*FRONT GRILLE	Cracked/Cut	681.00 FL	*364.00 FL
9	1		*FRONT BUMPER	Cracked	1,498.00 FL	*1,058.00 FL
10	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	298.00 FL	*- FL
11	1		*FRONT BUMPER GRILLE	Cut	892.00 FL	*241.70 FL
12	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	778.20 FL	*- FL
13	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	716.00 FL	*- FL
14	2		*FRONT BUMPER SIGNAL LAMP LH/RH	Not Necessary	698.20 FL	*- FL
15	2		*FRONT BUMPER SIGNAL LAMP GARNISH LH/RH	Not Necessary	642.00 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Torn	341.00 FL	*208.00 FL
17	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,049.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Cracked	2,485.00 FL	*1,140.45 FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	429.00 FL	*234.75 FL
20	1		*INTER-COOLER ASSY	Bent/Punctured	2,581.00 FL	*714.45 FL
21	1		*A/C CONDENSOR	Punctured/Bent	1,984.00 FL	*631.35 FL
22	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	985.00 FL	*- FL
23	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	391.00 FL	*- FL
24	1		*RADIATOR ASSY	Bent/Punctured	2,312.00 FL	*918.10 FL
25	1		*RADIATOR FAN COMPLETE	Not Necessary	1,984.00 FL	*- FL
26	1		*TAILGATE	Not Necessary	2,840.00 FL	*- FL
27	1		*TAILGATE VOLKSWAGEN LOGO	Not Necessary	110.00 FL	*- FL
28	1		*TAILGATE TSI EMBLEM	Not Necessary	134.00 FL	*- FL
29	1		*TAILGATE LOCK	Not Necessary	294.00 FL	*- FL
30	1		*TAILGATE INNER TRIM BOARD	Not Necessary	845.00 FL	*- FL
31	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	295.00 FL	*- FL
32	2		*TAILGATE DAMPER LH/RH	Not Necessary	1,658.00 FL	*- FL
33	1		*TAILGATE WEATHER STRIP	Not Necessary	342.00 FL	*- FL
34	2		*TAIL LAMP LH/RH	Not Necessary	3,784.00 FL	*- FL
35	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	268.00 FL	*- FL
36	1		*REAR BUMPER	Distorted	1,812.00 FL	*1,122.30 FL
37	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	379.20 FL	*- FL
38	1		*REAR BUMPER LOWER LID	No such part	1,092.30 FL	*- FL
39	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	204.00 FL	*- FL
40	2		*REAR BUMPER NO PLATE LAMP LH/RH	Not Necessary	384.00 FL	*- FL
41	1		*REAR BUMPER UNDER COVER	Not Necessary	395.00 FL	*- FL
42	1		*REAR REINFORCEMENT BAR	Not Necessary	940.00 FL	*- FL
43	1		*REAR BUMPER SPONGE	Not fitted	320.00 FL	*- FL
44	1		*REAR END PANEL	Repair	1,470.00 FL	*- FL
45	1		*REAR END PANEL TOP GARNISH	Not Necessary	312.00 FL	*- FL
46	1		*SPARE WHEEL PANEL	Not Necessary	1,782.00 FL	*- FL
47	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	782.00 FL	*- FL
48	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	529.00 FL	*- FL
49	1		*REAR EXHAUST PIPE	Not Necessary	1,984.00 FL	*- FL
50	1		*REAR EXHAUST MOUNTING	Not Necessary	209.10 FL	*- FL
51	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	495.10 FL	*- FL
52	1		*KEYLESS SENSOR	Not Necessary	324.51 FL	*- FL
53	1		*KEYLESS BUZZER	Not Necessary	301.91 FL	*- FL
54	2		*HEAD LAMP TOP PANEL LH/RH	Bent	829.00 FL	*241.54 FL
55	1		*REAR BUMPER CENTER BRACKET	Broken	410.00 FL	*195.40 FL
56	1		*FRONT & REAR NUMBER PLATE & GARNISH	Bent 1Pc/Not Necessary 1Pc	200.00 FS	*45.00 FS
57	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
58	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
60	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
61	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
62	1		*COOLANT	Not Necessary	100.00 FS	*- FS
63	1		*SET REAR REVERSE SENSOR	Serviceable	300.00 FS	*- FS
64	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
65	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
66	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
68	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$)	60,075.72	10,515.29
- List Item Discount on L Items 10.00/10.00% (\$)	5,818.57		1,040.03
	Total Parts (\$)	54,257.15	9,475.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,000.00	600.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,000.00	300.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,000.00	400.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO SUPPLY A/C CONDENSOR TO FACILITATE REPAIRS	New	200.00	120.00
8	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS }	New	200.00	50.00
9	TO RNR INTER-COOLER ASSY TO FACILITATE REPAIRS }	New	200.00	0.00
10	TO RNR REVERSE CAMERA	New	100.00	0.00
11	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	0.00
12	TO RNR REAR BOOT MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
13	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
14	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
15	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
16	TO RNR REVERSE SENSOR TOASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (S\$)			10,770.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >