

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000877/AEA3Q2**Date:** 09/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210019158
Claimant Vehicle No :	SJY3728P	Insured Vehicle No :	SMJ4429P
Date of Loss:	22/01/2022	Nature of Claim:	TP
		Claim No:	4325259030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY3728P	Engine No:	3ZZB027043
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106183913
Reg. Date:	25/08/2010 (Man. Year: 2010)	Odometer:	55009 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	LAUFENN 6 mm	Rear Left Side:	LAUFENN 6 mm
Front Right Side:	LAUFENN 6 mm	Rear Right Side:	LAUFENN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,524.87	2,737.55	787.32	22.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,660.00	1,620.00	49.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,804.87	4,397.55	2,407.32	35.38
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	6,804.87	3,500.00	3,304.87	48.57
+ GST 7.00/7.00% (S\$)	476.34	245.00	231.34	48.57
Nett Amount (S\$)	7,281.21	3,745.00	3,536.21	48.57
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,112.45		
Global Sum Settlement (S\$)		4,110.00		

INSPECTION

Date of Assignment: 24/01/2022

Date Inspected: 24/01/2022

Estimated Period of Repair: 6.0 days

Inspected At:

MG SOLUTION PTE LTD
23 KAKI BUKIT AVE 4
(SOUTH WING) #02-03B
VICOM INSPECTION CENTRE,
SINGAPORE 415933

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	769.60 FL	*769.60 FL
2	1		*BOOTLID LOGO	Necessary	80.00 FL	*80.00 FL
3	1		*BOOTLID EMBLEM COROLLA	Necessary	62.40 FL	*62.40 FL
4	1		*BOOTLID EMBLEM ALTIS	Necessary	55.30 FL	*55.30 FL
5	1		*BOOTLID EMBLEM 1.6	Necessary	55.00 FL	*55.00 FL
6	1		*BOOTLID TOP LOCK	Damaged	162.20 FL	*162.20 FL
7	1		*BOOTLID WEATHERSTRIP	Not Necessary	222.30 FL	*- FL
8	1		*REAR BUMPER	Deformed	588.70 FL	*588.70 FL
9	2		*REAR BUMPER SIDE RETAINER FRONT	Not Necessary	124.80 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINER REAR	Necessary	110.40 FL	*110.40 FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	180.00 FL	*- FL
12	1		*REAR BUMPER BRACKET	N/S Dented	260.00 FL	*130.00 FL
13	1		*REAR BUMPER SPONGE WITH PROTECTOR BAR	Cracked	166.80 FL	*166.80 FL
14	1		*TAILLAMP	Cut	375.00 FL	*375.00 FL
15	1		*REAR END PANEL	Dented	708.00 FL	*708.00 FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	126.00 FL	*- FL
17	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
18	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
19	1		*SET TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
20	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
21	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
22	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,536.50	3,553.40
- List Item Discount on L Items 25.00/25.00% (\$)	1,011.63	815.85
Total Parts (\$)	3,524.87	2,737.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	TRANFER BOOTLID MECHANISM	New	120.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
8	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
Gross Labour Cost (\$\$)			3,280.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >