

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III22000880/VVF3E2  
**Date:** 24/02/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0003256\_01  
**Claimant Vehicle No :** SMD7120R **Insured Vehicle No :** PC7674D  
Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: MFL2022D0000553

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD7120R**  
Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B21600678  
Reg. Date: 21/11/2016 (Man. Year: 2016) Chassis No: MRHFC5650GT000508  
Colour: Blue Odometer: 0 km  
Engine Capacity: 1597 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/45Z R17 Rear Tyre Size: 235/45Z R17  
Front Left Side: KAPSEN 5 mm Rear Left Side: KAPSEN 5 mm  
Front Right Side: KAPSEN 5 mm Rear Right Side: KAPSEN 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 25/01/2022  
Date Inspected: 26/01/2022 Inspected At: SPEEDWERKZ PTE LTD (HQ)  
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre  
Singapore 147807  
Estimated Period of Repair: 0.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 24 Feb 2022)

**Parts:**            143                    HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's          (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMD7120R)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**