

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG22000881/EVY3E2

Date: 18/05/2022

REFERENCE

Insured/Claimant:	YAP ZONG XING, ERIC	Policy No:	7210154384		
Date of Loss:	22/01/2022	Nature of Claim:	OD	Claim No:	1246391977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM5128J		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	DEM034426
Reg. Date:	28/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF5XNA002843
Colour:	White	Odometer:	1088 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$188,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,776.00	8,712.72	15,063.28	63.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,952.00	6,172.00	6,780.00	52.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,728.00	14,884.72	21,843.28	59.47
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	35,928.00	14,084.72	21,843.28	60.80
+ GST 7.00/7.00% (S\$)	2,514.96	985.93	1,529.03	60.80
Nett Amount (S\$)	38,442.96	15,070.65	23,372.31	60.80

INSPECTION

Date of Assignment:	25/01/2022		
Date Inspected:	25/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	72.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
5	1		*FRONT BUMPER AIR GRILLE TRIM - LH	Not Necessary	54.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
7	1		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
8	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	15.00 FS	*- FS
9	1		*FRONT FENDER - LH	Dented	1,189.00 FS	*951.20 FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
11	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	83.00 FS	*- FS
12	1		*FRONT FENDER BRACKET - LH	Not Necessary	41.00 FS	*- FS
13	1		*FRONT FENDER DEFORMATION BRACKET - LH	Not Necessary	55.00 FS	*- FS
14	1		*FRONT FENDER BRACE - LH	Not Necessary	132.00 FS	*- FS
15	1		*FRONT FENDER CENTER BRACKET - LH	Not Necessary	40.00 FS	*- FS
16	1		*FRONT FENDER CHROME TRIM - LH	Necessary	171.00 FS	*136.40 FS
17	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	299.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER - LH	Not Necessary	82.00 FS	*- FS
19	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	39.00 FS	*- FS
20	1		*FRONT WHEEL SPOILER BRACKET - LH	Not Necessary	27.00 FS	*- FS
21	1		*FRONT FENDER STONE CHIP GUARD - LH	Cut	57.00 FS	*45.28 FS
22	1		*FRONT WIND MIRROR MOUNTING - LH	Broken	2,137.00 FS	*1,709.60 FS
23	1		*FRONT WIND MIRROR COVER - LH	Missing	308.00 FS	*246.40 FS
24	1		*FRONT WIND MIRROR - LH	Broken	1,298.00 FS	*1,038.40 FS
25	1		*ROOF CHROME MOLDING - LH	Cut	706.00 FS	*564.80 FS
26	1		*FRONT DOOR UPPER PROTECT SEAL - LH	Not Necessary	172.00 FS	*- FS
27	1		*FRONT DOOR WINDOW SLOT SEAL - LH	Not Necessary	446.00 FS	*- FS
28	1		*FRONT WATER DEFLECTOR STRIP - LH	Not Necessary	75.00 FS	*- FS
29	1		*FRONT DOOR CONER TRIM - LH	Cut	51.00 FS	*40.40 FS
30	1		*FRONT DOOR CHROME TRIM - LH	Necessary	171.00 FS	*136.40 FS
31	1		*FRONT DOOR WINDOW - LH	Not Necessary	322.00 FS	*- FS
32	1		*FRONT WINDSCREEN	Not Necessary	1,625.00 FS	*- FS
33	1		*RAIN SENSOR FOIL	Not Necessary	130.00 FS	*- FS
34	1		*RETAINING SPRING	Not Necessary	24.00 FS	*- FS
35	1		*SPRING CLIP	Not Necessary	23.00 FS	*- FS
36	1		*FRONT WINDSCREEN CAMERA SILICONE PAD	Not Necessary	123.00 FS	*- FS
37	1		*PRIMER	Not Necessary	22.00 FS	*- FS
38	1		*FRONT RIM - LH	Cut	1,889.00 FS	*1,511.20 FS
39	1		*SILL PANEL TRIM ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
40	1		*SILL PANEL TRIM ADHESIVE TAPES	Necessary	221.00 FS	*176.80 FS
41	1		*FRONT HEADLIGHT - LH	Not Necessary	8,172.00 FS	*- FS
42	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
43	1		*SUNDRIES	Necessary	350.00 FS	*52.64 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 23,776.00 8,712.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY AND DOOR COMPONENTS	New	280.00	280.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	0.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN AND LHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	0.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET AND LHS FRONT DOOR. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,250.00
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS UPPER A-PILLAR AND LHS SILL PANEL TRIM	New	6,000.00	3,450.00
9	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			12,952.00	6,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >