

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD22000885/DPA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2021-00001721
Claimant Vehicle No : SGT7277J **Insured Vehicle No :** FBJ3580X
 Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: 1202200000975

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGT7277J**
 Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) Engine No: 2ZR2G67059
 Reg. Date: 01/02/2021 (Man. Year: 2020) Chassis No: ZWR800431979
 Colour: Silver Odometer: 42315 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,498.14	2,051.75	26,446.39	92.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,420.00	1,400.00	5,020.00	78.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,918.14	3,451.75	31,466.39	90.11
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	34,918.14	2,700.00	32,218.14	92.27
+ GST 7.00/7.00% (S\$)	2,444.27	189.00	2,255.27	92.27
Nett Amount (S\$)	37,362.41	2,889.00	34,473.41	92.27
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,325.45		

INSPECTION

Date of Assignment: 25/01/2022
 Date Inspected: 25/01/2022 Inspected At: C. S. Ong Auto Pte Ltd (HQ)
 BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK
 AUTOPOINT
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jul 2022)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGT7277J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,471.50 FL	*- FL
2	2		*BONNET HINGE LH/RH	Not Necessary	174.80 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	339.20 FL	*- FL
4	1		*HEAD LAMP RH	Not Necessary	4,800.80 FL	*- FL
5	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	329.80 FL	*- FL
6	1		*HEAD LAMP PANEL RH	Not Necessary	459.10 FL	*- FL
7	1		*FRONT BUMPER	Not Necessary	1,480.80 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	344.66 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	489.51 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP CHROME RH	Not Necessary	349.10 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP CHROME RH	Not Necessary	331.30 FL	*- FL
12	1		*FRONT BUMPER SPONGE	Not Necessary	282.20 FL	*- FL
13	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,049.90 FL	*- FL
14	1		*FRONT FENDER RH	Dented	2,928.00 FL	*911.20 FL
15	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	342.00 FL	*102.50 FL
16	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	428.19 FL	*- FL
17	1		*A PILLAR RH	Not Necessary	1,982.40 FL	*- FL
18	1		*A PILLAR QUARTER GLASS MOULDING RH	Not Necessary	298.10 FL	*- FL
19	1		*FRONT DOOR RH	Repair	1,829.40 FL	*- FL
20	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	115.36 FL	*- FL
21	1		*FRONT DOOR WEATHER STRIP RH	Not Necessary	293.40 FL	*- FL
22	1		*FRONT DOOR BLACK STICKER RH	Not Necessary	84.50 FL	*- FL
23	1		*FRONT RIM RH	Cut	1,873.50 FS	*500.00 FS
24	1		*FRONT WHEEL BEARING & HUB ASSY RH	Not Necessary	461.50 FL	*- FL
25	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,091.30 FL	*- FL
26	1		*FRONT LOWER ARM RH	Not Necessary	681.20 FL	*- FL
27	1		*FRONT ABSORBER RH	Not Necessary	785.90 FL	*- FL
28	1		*FRONT STABILIZER LINKAGE RH	Not Necessary	176.78 FL	*- FL
29	1		*FRONT STABILIZER BAR	Not Necessary	411.60 FL	*- FL
30	1		*STEERING RACK & PINION ASSY	Not Necessary	2,901.50 FL	*- FL
31	1		*DRIVE SHAFT RH	Not Necessary	2,095.40 FL	*- FL
32	1		*FRONT WHEEL HOUSING RH	Not Necessary	1,982.40 FL	*- FL
33	1		*SIDE MIRROR ASSY RH	Cut / Damaged	2,198.41 FL	*1,055.30 FL
34	1		*SIDE SKIRT RH	Repair	1,429.51 FL	*- FL
35	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*A PILLAR QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*A PILLAR QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
41	1		*TYRE	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	37,103.02	2,569.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,604.88	517.25
Total Parts (\$\$)	28,498.14	2,051.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	300.00	0.00
6	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00
7	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
10	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	120.00	60.00
Gross Labour Cost (\$\$)			6,420.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >