

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000887/KVY3N2**Date:** 01/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00089122101

Claimant Vehicle No : SLB5401R **Insured Vehicle No :** GBH6344C

Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: SNM22D200550/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB5401R**

Make & Model: TOYOTA HARRIER, 2.0 Elegance (A) Engine No: 3ZRB730067

Reg. Date: 13/04/2016 (Man. Year: 2015) Chassis No: ZSU600072500

Colour: Metallic Pearl White Odometer: 127781 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65R17 Rear Tyre Size: 225/65R17

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,142.65	5,569.12	6,573.53	54.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,760.00	1,580.00	47.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,482.65	7,329.12	8,153.53	52.66
Approved Total (Overridden) (\$\$)		5,850.00		
(\$\$)	15,482.65	5,850.00	9,632.65	62.22
+ GST 7.00/7.00% (\$\$)	1,083.79	409.50	674.29	62.22
Nett Amount (\$\$)	16,566.44	6,259.50	10,306.94	62.22

INSPECTION

Date of Assignment: 25/01/2022

Date Inspected: 26/01/2022 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5401R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	1,881.30 FL	*1,881.30 FL
2	1		*FRONT DOOR TAPE OUTER TOP LH	Necessary	58.20 FL	*58.20 FL
3	1		*FRONT DOOR TAPE OUTER RR LH	Necessary	26.40 FL	*26.40 FL
4	1		*FRONT DOOR TAPE INNER TOP LH	Necessary	42.20 FL	*42.20 FL
5	1		*FRONT DOOR LOWER CHROME MLDG LH	Serviceable	158.70 FL	*- FL
6	1		*FRONT DOOR RUBBER (AT DOOR) LH	Serviceable	213.30 FL	*- FL
7	1		*FRONT DOOR RUBBER (AT DOOR) BTM LH	Serviceable	87.60 FL	*- FL
8	1		*FRONT DOOR LOCK LH	Repair	561.90 FL	*- FL
9	1		*REAR DOOR LH	Bent	1,550.40 FL	*1,550.40 FL
10	1		*REAR DOOR TAPE OUTER FRT LH	Necessary	26.40 FL	*26.40 FL
11	1		*REAR DOOR TAPE OUTER TOP LH	Necessary	47.40 FL	*47.40 FL
12	1		*REAR DOOR TAPE OUTER RR LH	Necessary	26.40 FL	*26.40 FL
13	1		*REAR DOOR TAPE INNER FRT LH	Necessary	31.80 FL	*31.80 FL
14	1		*REAR DOOR TAPE INNER TOP LH	Necessary	18.50 FL	*18.50 FL
15	1		*REAR DOOR LWR CHROE MLDG LH	Dented	142.50 FL	*142.50 FL
16	1		*REAR DOOR RUBBER (AT DOOR) LH	Serviceable	181.60 FL	*- FL
17	1		*REAR DOOR RUBBER (AT DOOR) BTM LH	Serviceable	55.50 FL	*- FL
18	1		*REAR DOOR RUBBER (AT DOOR) LH	Serviceable	346.10 FL	*- FL
19	2		*REAR DOOR HINGE LH TOP & BTM	Repair	197.80 FL	*- FL
20	1		*REAR DOOR LOCK LH	Repair	667.40 FL	*- FL
21	1		*REAR DOOR WINDOW REGULATOR LH	Serviceable	231.00 FL	*- FL
22	1		*REAR DOOR WINDOW MOTOR LH	Serviceable	974.10 FL	*- FL
23	1		*SIDE SKIRT LH	Serviceable	734.20 FL	*- FL
24	1		*REAR FENDER LH	Repair	1,531.10 FL	*- FL
25	1		*REAR FENDER COWLING LH	Serviceable	169.80 FL	*- FL
26	8		*REAR FENDER COWLING CLIPS	Not Necessary	36.00 FL	*- FL
27	1		*REAR BUMPER	Dented/Cut	1,511.70 FL	*1,381.00 FL
28	1		*REAR BUMPER LOWER GARNISH	No such part	411.70 FL	*- FL
29	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	82.70 FL	*- FL
30	1		*REAR BUMPER SIDE SILL LH	Serviceable	79.00 FL	*- FL
31	8		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
32	1		*REAR WHEEL BEARING + HUB LH	Not Necessary	1,008.80 FL	*- FL
33	1		*SPORTS RIM LHR (R17)	Dented	2,982.70 FL	*2,157.00 FL
34	1		*INNER SEAL	Not Necessary	20.00 FS	*- FS
35	1		*WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
36	1		*TYRE LHF (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,170.20	7,425.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,027.55	1,856.38
Total Parts (\$\$)	12,142.65	5,569.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
2	TO DISMANTLE AND TRANSFER DOOR FITTING AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR	New	120.00	60.00
3	TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS	New	60.00	0.00
4	TO REMOVE AND REINSTALL CUSHIONS SEATS,BACKREST,INNER TRIM GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	80.00
5	TO DISMANTLE,REPLACE AND REINSTALL UNDERCARRIAGE	New	120.00	0.00
6	TO REMOVE AND REINSTALL/REPLACE FUEL TANK,FIXTURE AND ATTACHMENTS	New	80.00	0.00
7	TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG,PASSENGER AIR-BAG,SEATBELTS AND AIR-BAG CONTROL BOX	New	180.00	0.00
8	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	60.00	50.00
9	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	200.00	0.00
10	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
11	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER LH TO KNOCK & REPAIR REAR FENDER INNER ROCKER PANEL INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	1,000.00	600.00
12	TO SPRAY FRONT DOOR LH,REAR DOOR LH,SIDE SKIRT LH,ROCKER PANEL LH,REAR FENDER LH,REAR BUMPER	New	1,200.00	880.00
Gross Labour Cost (\$\$)			3,340.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >