

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000895/KQY3N2**Date:** 15/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00119112101
Claimant Vehicle No :	SLN5407L	Insured Vehicle No :	YP8173B
Date of Loss:	24/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200619/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN5407L	Engine No:	1NZR503586
Make & Model:	TOYOTA AQUA, 1.5 E 1.5 SA (A)	Chassis No:	NHP106587753
Reg. Date:	08/05/2017 (Man. Year: 2017)	Odometer:	286734 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/55 R16	Rear Tyre Size:	175/55
Front Left Side:	INTERTRAC 3 mm	Rear Left Side:	INTERTRAC 3 mm
Front Right Side:	INTERTRAC 3 mm	Rear Right Side:	INTERTRAC 3 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,722.25	3,265.50	3,456.75	51.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	860.00	850.00	49.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,432.25	4,125.50	4,306.75	51.07
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	8,432.25	3,300.00	5,132.25	60.86
+ GST 7.00/7.00% (\$\$)	590.26	231.00	359.26	60.86
Nett Amount (\$\$)	9,022.51	3,531.00	5,491.51	60.86

INSPECTION

Date of Assignment:	25/01/2022	
Date Inspected:	25/01/2022 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Mar 2022)	
Parts:	N/A	TOYOTA AQUA 1.5 E 1.5 SA (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN5407L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	1,241.00 FL	*- FL
2	1		*FRONT DOOR INNER TRIM BOARD RH	Serviceable	914.00 FL	*- FL
3	1		*FRONT DOOR FRAME PROTECTIVE STICKER RH	Not Necessary	50.00 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE RH	Dented/Cut	375.00 FL	*375.00 FL
5	1		*FRONT DOOR GLASS LOWER OUTER MOULDING RH	Distorted	65.00 FL	*65.00 FL
6	1		*FRONT DOOR INNER LOCK RH	Repair	560.00 FL	*- FL
7	1		*REAR DOOR RH	Bent	1,045.00 FL	*1,045.00 FL
8	1		*REAR DOOR INNER TRIM BOARD RH	Buckled	763.00 FL	*763.00 FL
9	1		*REAR DOOR OUTER HANDLE RH	Serviceable	375.00 FL	*- FL
10	1		*REAR DOOR LOCK RH	Repair	560.00 FL	*- FL
11	1		*REAR DOOR FRAME PROTECTIVE STICKER RH	Necessary	50.00 FL	*50.00 FL
12	1		*REAR DOOR GLASS RH	Shattered	863.00 FL	*863.00 FL
13	1		*REAR DOOR GLASS LOWER OUTER MOULDING RH	Bent	65.00 FL	*65.00 FL
14	1		*REAR DOOR REGULATOR RH	Bent	201.00 FL	*201.00 FL
15	1		*REAR DOOR UPPER HINGE RH	Repair	90.00 FL	*- FL
16	1		*REAR DOOR LOWER HINGE RH	Repair	90.00 FL	*- FL
17	1		*REAR DOOR CHECKER RH	Serviceable	195.00 FL	*- FL
18	1		*REAR DOOR SPEAKER RH	Serviceable	454.00 FL	*- FL
19	1		*FRONT DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	60.00 FS	*- FS
20	1		*REAR DOOR INNER TRIM BOARD CLIPS RH	Necessary	60.00 FS	*60.00 FS
21	1		*REAR DOOR WINDOW MOTOR RH	Jammed	847.00 FL	*847.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,923.00	4,334.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,200.75	1,068.50
Total Parts (\$)	6,722.25	3,265.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	600.00	300.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH,REAR DOOR RH & ETC	New	600.00	450.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC.BACK TO ORIGINAL OPERATIONS	New	120.00	0.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC.BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS & ETC	New	120.00	30.00
6	TO CHECK WIRING & CENTRAL LOCKING SYSTEM	New	150.00	20.00
Gross Labour Cost (\$\$)			1,710.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >