

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000898/Bqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 16/03/2022 SINGAPORE 068811 ATTN: HO WINNIE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 1097P** SMF 1705H Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03RV1 Excess (\$) 0.00 HO WINNIE **Assign Date** 25/01/2022 Assign From **Vehicle Particulars & Condition** 2. BMW 420I GRAN COUPE Make & Model 1998 C.C 2018 HIDDEN Engine No. Year of Reg. WBA4H32040BP26972 WHITE Chassis No. Colour 17378 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/45 R18 BRIDGESTONE 5 mm L/H Front Tyre 225/45 R18 BRIDGESTONE 5 mm 255/40 R18 BRIDGESTONE R/H Rear Tyre 5 mm **BRIDGESTONE** L/H Rear Tyre 255/40 R18 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. 5. **General Information** 23/01/2022 07/02/2022 (02:00 PM) Inspect Date / Time Accident Date KING'S AUTO REPAIR & SERVICE PTE LTD Survey held at 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721 Remarks 5a. A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

Report Ref No. CS3/ASM22000898/Bqy3e2

Estimate Days of Repair

Inspected By

Cin

5b.

LIM TEOW GUAN

Tu

K.K.LAU CPT(RET)

Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR:

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days