

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22000901/Gvy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	04/02/2022		
	ATTN: TAN JUN H	ONG		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 9177P	Veh. Inspected	t	FBP 6120P	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S2M03RUP	Excess (\$)		0.00	
	Assign From	TAN JUN HONG	Assign Date		25/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA YS-125	c.c		125	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	LBPRE331000018721	Colour		RED	
	Odometer	27102 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	2.75-18	CST		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	3.60-18	VEE RUBBER		6 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY AND FRONT PORTION.					
5.	. General Information					
	Accident Date	19/01/2022	Inspect Date /	Time	25/01/2022 (04:00 PM)	
	Survey held at	464 Macpherson Road Singapore	e 368182			
	Repairer	Repairer MOTO 51 PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22000901/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor