

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17009141/AQY3E2-1

Date: 26/01/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100468826
Claimant Vehicle No :	SGX7161M	Insured Vehicle No :	SLC9426M
Date of Loss:	07/05/2017	Nature of Claim:	TP
		Claim No:	1633595010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX7161M	Engine No:	2AZF057046
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500043448
Reg. Date:	03/09/2007 (Man. Year: 2007)	Odometer:	181387 km
Colour:	Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,547.28	3,956.60	11,590.68	74.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	2,310.00	2,240.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,097.28	6,266.60	13,830.68	68.82
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	20,097.28	5,000.00	15,097.28	75.12
+ GST 7.00/7.00% (S\$)	1,406.81	350.00	1,056.81	75.12
Nett Amount (S\$)	21,504.09	5,350.00	16,154.09	75.12

INSPECTION

Date of Assignment: 11/05/2017

Date Inspected: 11/05/2017 Inspected At:

Estimated Period of Repair: 5.0 days

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,712.40 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	226.90 FL	*- FL
3	1		*FRONT LH ABS SENSOR	Not Necessary	397.10 FL	*- FL
4	1		*FRONT LH DOOR	Dented	1,004.00 FL	*1,004.00 FL
5	1		*FRONT LH DOOR MECHANISM LOCK	Not Necessary	509.00 FL	*- FL
6	1		*FRONT LH DOOR TRIM BOARD	Not Necessary	780.00 FL	*- FL
7	1		*FRONT LH DOOR WEATHER STRIP	Not Necessary	215.00 FL	*- FL
8	1		*FRONT LH FENDER	Dented	700.00 FL	*700.00 FL
9	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	372.25 FL	*- FL
10	1		*FRONT LH HEADLAMP	Not Necessary	1,912.40 FL	*- FL
11	1		*FRONT LH KNUCKLE ARM	Damaged	581.60 FL	*581.60 FL
12	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	161.40 FL	*161.40 FL
13	1		*FRONT LH LOWER ARM	Bent	374.40 FL	*374.40 FL
14	1		*FRONT LH LOWER ARM BALL JOINT	Bent	166.78 FL	*166.78 FL
15	1		*FRONT LH SHOCK ABSORBER	Bent	372.55 FL	*372.55 FL
16	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Not Necessary	261.60 FL	*- FL
17	1		*FRONT LH STABILIZER LINKAGE	Not Necessary	195.40 FL	*- FL
18	1		*FRONT LH WHEEL HUB BEARING	Not Necessary	152.70 FL	*- FL
19	1		*REAR AXLE ASSY	Not Necessary	3,027.70 FL	*- FL
20	1		*REAR BUMPER	Repair	1,125.70 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	123.40 FL	*- FL
22	1		*REAR LH FENDER	Repair	971.20 FL	*- FL
23	1		*REAR LH FENDER INNER SHIELD	Not Necessary	231.70 FL	*- FL
24	1		*REAR LH SHOCK ABSORBER	Not Necessary	182.55 FL	*- FL
25	1		*REAR LH WHEEL HUB BEARING	Damaged	581.40 FL	*581.40 FL
26	1		*SLIDING LH DOOR	Repair	1,217.25 FL	*- FL
27	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*SET FRONT LH DOOR TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*FRONT LH SPORT RIM	Cut	600.00 FS	*500.00 FS
31	1		*FRONT LH TYRE	Not Necessary	480.00 FS	*- FS
32	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
33	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
34	1		*REAR LH SPORT RIM	Cut	600.00 FS	*500.00 FS
35	1		*REAR LH TYRE	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,936.38	4,942.13
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,389.10	985.53
Total Parts (\$\$)	15,547.28	3,956.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	200.00	80.00
2	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK PINION	New	300.00	220.00
3	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	450.00	100.00
4	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	180.00	80.00
5	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	100.00	0.00
6	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	100.00	80.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,600.00	1,000.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	700.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
Gross Labour Cost (\$\$)			4,550.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >