



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Z FA 2630000 6H45
 288.

TP Sompoo Hui Rong

Vehicle No. GBJ2742C FIAT DOBLO

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BUMPER <i>Distorted.</i>		781.00	/
2	REAR BUMPER SIDE BRACKET LH & RH @\$152.00 <i>LH mod</i>		304.00	90.
2	REAR BUMPER REFLECTOR LH & RH @\$ 98.60 <i>LH Missing</i>		197.20	98.60.
1	REAR BUMPER REINFORCEMENT <i>Dented</i>		594.20	/
1	REAR BUMPER INNER FRAME <i>HP new</i>		298.00	X.
1	REAR DOOR LH <i>Dented.</i>		1798.20	/
1	REAR DOOR HANDLE LH <i>New</i>		589.00	X.
1	REAR DOOR INNER TRIM BOARD LH <i>New</i>		673.00	/
1	REAR DOOR WIPER MOTOR <i>Dented.</i>		385.00	/
1	REAR DOOR RH		1820.00	/
1	REAR DOOR INNER LOCK TOP		285.00	/
1	REAR DOOR INNER LOCK LOWER		285.00	/
1	REAR DOOR FIAT EMBLEM		98.00	/
1	REAR DOOR INNER TRIM BOARD RH		673.00	/
1	REAR DOOR EDGE WEATHERSTRIP		185.00	X.
1	REAR END PANEL <i>Reps</i>	5279.20	798.00	X.
1	REAR TAILLAMP LH <i>nt</i>	4751.28	610.00	/
1	REAR TAILLAMP PANEL LH <i>Reps</i>		345.00	X.
1	REAR WINDSCREEN <i>Shattered.</i>		922.20	/
			11640.80	
less 10%			1164.08	10%
			10476.72	
SPECIAL NETT ITEM				
1 SET	REVERSE SENSOR <i>Dented</i>		280.00	200
1 SET	REAR BUMPER CLIPS <i>New</i>		100.00	30
1 SET	REAR CAR PLATE WITH COVER <i>Dented</i>	575	70.00	/
1	REAR WINDSCREEN SEALANT <i>New</i>		80.00	60
1	REAR DOOR "70KM/H" STICKER LH <i>New</i>		70.00	15
1	REAR DOOR "6PAX" STICKER <i>New</i>		70.00	X.
	<i>New Windscreen Solar Film. New</i>		300	200.
Total Parts			11146.72	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Vehicle No. GBJ2742C FIAT DOBLO

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00 700	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00 800	
3	To remove and refix wiring at damaged areas	120.00 30	
4	To perform anti rust treatment on affected areas	120.00 60	
5	To conduct water seepage test	150.00 X	
6	To remove and replace rear door windscreen lh	150.00 100	
7	To remove and refix rear compartment item	120.00 60	1800
8	To remove and replace reverse sensor	150.00 50	
	Labour Total :	4210.00	
TOTAL (PARTS & LABOUR):		15356.72	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 7126.28

L/S: 5.7K

0.6 Days

5.7K