



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 2742C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DISTORTED	781.00	781.00
2	REAR BUMPER SIDE BRACKET LH & RH @\$152.00	N/S DAMAGED	304.00	90.00
2	REAR BUMPER REFLECTOR LH & RH @\$98.60	N/S MISSING	197.20	98.60
1	REAR BUMPER REINFORCEMENT	DENTED	594.20	594.20
1	REAR BUMPER INNER FRAME	NOT NECESSARY	298.00	-
1	REAR DOOR LH	DENTED	1,798.20	1,798.20
1	REAR DOOR HANDLE LH	NOT NECESSARY	589.00	-
1	REAR DOOR INNER TRIM BOARD LH	NOT NECESSARY	673.00	-
1	REAR DOOR WIPER MOTOR	DAMAGED	385.00	385.00
1	REAR DOOR RH	NOT NECESSARY	1,820.00	-
1	REAR DOOR INNER LOCK TOP	NOT NECESSARY	285.00	-
1	REAR DOOR INNER LOCK LOWER	NOT NECESSARY	285.00	-
1	REAR DOOR FIAT EMBLEM	NOT NECESSARY	98.00	-
1	REAR DOOR INNER TRIM BOARD RH	NOT NECESSARY	673.00	-
1	REAR DOOR EDGE WEATHERSTRIP	NOT NECESSARY	185.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	798.00	-
1	REAR TAILLAMP LH	CUT	610.00	610.00
1	REAR TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	345.00	-
1	REAR WINDSCREEN	SHATTERED	922.20	922.20
	LESS 10% DISCOUNT		-1,164.08	-527.92
			10,476.72	4,751.28
<b>SPECIAL NETT ITEMS</b>				
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET REAR CAR PLATE WITH COVER (SN)	DENTED	70.00	70.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR DOOR "70KM/H" STICKER LH (SN)	NECESSARY	70.00	15.00
1	REAR DOOR "6PAX" STICKER (SN)	NOT NECESSARY	70.00	-

Report Ref No. CS/SMO22000903/Any3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	300.00	200.00
			970.00	575.00
	<b>LABOUR</b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TAILLAMP PANEL LH.		1,800.00	700.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.		1,600.00	800.00
	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS.		120.00	30.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.		120.00	60.00
	TO CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	150.00	-
	TO REMOVE AND REPLACE REAR DOOR WINDSCREEN LH.		150.00	100.00
	TO REMOVE AND REFIX REAR COMPARTMENT ITEM.		120.00	60.00
TO REMOVE AND REPLACE REVERSE SENSOR.		150.00	50.00	
			4,210.00	1,800.00
<b>GRAND TOTAL</b>			<b>15,656.72</b>	<b>7,126.28</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,700.00</b>

Report Ref No. CS/SMO22000903/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.