

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22000904/EVY3E2

Date: 23/05/2022

REFERENCE

Insured/Claimant:	TAN GUAN LONG	Policy No:	2070052821	
Date of Loss:	21/01/2022	Nature of Claim:	OD	Claim No: 9084469871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT440D		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZC33312
Reg. Date:	25/03/2020 (Man. Year: 2019)	Chassis No:	WAUZZZ8V6KA122373
Colour:	Blue	Odometer:	18939 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,848.00	16,116.72	11,731.28	42.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,552.00	3,842.00	6,710.00	63.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,400.00	19,958.72	18,441.28	48.02
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	38,100.00	19,658.72	18,441.28	48.40
+ GST 7.00/7.00% (S\$)	2,667.00	1,376.11	1,290.89	48.40
Nett Amount (S\$)	40,767.00	21,034.83	19,732.17	48.40

INSPECTION

Date of Assignment:	26/01/2022		
Date Inspected:	25/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
4	1		*FRONT BUMPE RGRILLE - CENTER	Broken	179.00 FS	*143.20 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Broken	571.00 FS	*456.80 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	318.00 FS	*- FS
7	1		*FRONT BUMPER TRIM COVER - RH	Not Necessary	182.00 FS	*- FS
8	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	42.00 FS	*- FS
9	1		*RADIATOR GRILLE	Broken	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Broken	210.00 FS	*168.00 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	210.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	136.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	211.00 FS	*168.80 FS
15	1		*HORN - RH	Not Necessary	213.00 FS	*- FS
16	1		*FRONT FENDER - RH	Dented	954.00 FS	*763.20 FS
17	5		*POP RIVET	Necessary	19.00 FS	*15.20 FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH	Necessary	46.00 FS	*36.40 FS
20	1		*FRONT FENDER BRACE - RH	Bent	107.00 FS	*85.60 FS
21	1		*FRONT FENDER BRACKET END - RH	Bent	31.00 FS	*24.24 FS
22	1		*FRONT WHEEL HOUSING LINER - RH	Broken	183.00 FS	*146.40 FS
23	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
24	1		*BONNET	Dented	3,134.00 FS	*2,507.20 FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
26	1		*BONNET CATCH HOOK	Not Necessary	100.00 FS	*- FS
27	2		*BONNET STRIKER - LH / RH	Not Necessary	246.00 FS	*- FS
28	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
29	1		*BONNET CATCH HOOK LOWER	Not Necessary	71.00 FS	*- FS
30	2		*BONNET MICRO - SWITCH	Not Necessary	455.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
32	1		*BONNET RELEASE LEVER COVER	Not Necessary	11.00 FS	*- FS
33	1		*HEADLIGHT - RH	Broken	5,455.00 FS	*4,364.00 FS
34	1		*LIFT CYLINDER - RH	Not Necessary	156.00 FS	*- FS
35	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
36	1		*LOCK CARRIER	Not Necessary	806.00 FS	*- FS
37	1		*A/C CONDENSER	Not Necessary	569.00 FS	*- FS
38	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
39	1		*ADDITIONAL RADIATOR	Not Necessary	959.00 FS	*- FS
40	1		*RADIATOR	Not Necessary	1,061.00 FS	*- FS
41	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
42	1		*RADIATOR AIR GUIDE - RH	Broken	28.00 FS	*22.16 FS
43	1		*RADIATOR SEAL - RH OUTER	Not Necessary	9.00 FS	*- FS
44	1		*RADIATOR AIR GUIDE - UPPER CENTER	Not Necessary	14.00 FS	*- FS
45	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
46	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
47	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
48	1		*SUNDRIES	Necessary	300.00 FS	*11.20 FS
49	1		*RADIATOR AUR GUID-LH (Supplementary)	Broken	28.00 FS	*22.16 FS
50	1		*LED HEADKIGHT-LH (Supplementary)	Cracked	5,455.00 FS	*4,364.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **27,848.00** **16,116.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, AND RADIATOR. CHECK ELECTRICAL AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	1,500.00
5	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE. (Supplementary)	New	350.00	250.00
Gross Labour Cost (\$\$)			10,552.00	3,842.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >