

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22000909/AVY3N2**Date:** 19/05/2022**REFERENCE**

Insured/Claimant: SHARON TAN HWEI CHING (CHEN HUIZHEN) Policy No: 2070054657  
Date of Loss: 21/01/2022 Nature of Claim: OD Claim No: 9340482916SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLD7888X**  
Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC38056  
Reg. Date: 23/03/2020 (Man. Year: 2019) Chassis No: WAUZZZ8VXLA035349  
Colour: White Odometer: 52826 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$120,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	27,307.00	18,060.72	9,246.28	33.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,952.00	6,312.00	6,640.00	51.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>40,259.00</b>	<b>24,372.72</b>	<b>15,886.28</b>	<b>39.46</b>
<b>- Excess (S\$)</b>	300.00	300.00	0.00	0.00
<b>(S\$)</b>	39,959.00	24,072.72	15,886.28	39.76
<b>+ GST 7.00/7.00% (S\$)</b>	2,797.13	1,685.09	1,112.04	39.76
<b>Nett Amount (S\$)</b>	<b>42,756.13</b>	<b>25,757.81</b>	<b>16,998.32</b>	<b>39.76</b>

**INSPECTION**

Date of Assignment: 26/01/2022  
Date Inspected: 25/01/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	86.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	179.00 FS	*143.20 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Cracked	332.00 FS	*265.20 FS
6	1		*FRONT BUMPER CLOSING ELEMENT-LH/RH	N/s damaged	636.00 FS	*254.40 FS
7	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR CLOSING ELEMENT	Cracked	210.00 FS	*168.00 FS
9	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
10	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	420.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	211.00 FS	*168.80 FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	847.00 FS	*677.20 FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Cracked	136.00 FS	*108.80 FS
15	2		*HORN-LH/RH	Not Necessary	426.00 FS	*- FS
16	1		*BONNET	Buckled	3,370.00 FS	*2,696.00 FS
17	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
18	2		*BONNET HINGE-LH/RH	Bent	136.00 FS	*108.48 FS
19	2		*FRONT FENDER UPPER INNER COVER-LH/RH	Not Necessary	92.00 FS	*- FS
20	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
21	1		*BONNET CATCH HOOK UPPER	Bent	100.00 FS	*79.44 FS
22	2		*BONNET STRIKER-LH/RH	Not Necessary	246.00 FS	*- FS
23	1		*BONNET CATCH HOOK LOWER	Bent	71.00 FS	*56.32 FS
24	2		*BONNET MICRO SWITCH-LH/RH	Not Necessary	455.00 FS	*- FS
25	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
26	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
27	1		*BONNET SOUND ABSORBER	Not Necessary	244.00 FS	*- FS
28	1		*PLENUM CHAMBER	Not Necessary	199.00 FS	*- FS
29	2		*HEADLIGHT-LH/RH	Cracked	10,910.00 FS	*8,728.00 FS
30	2		*LIFT CYLINDER-LH/RH	Not Necessary	312.00 FS	*- FS
31	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
32	1		*LOCK CARRIER	Deformed	806.00 FS	*644.80 FS
33	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
34	1		*A/C CONDENSER	Puncture	569.00 FS	*454.80 FS
35	1		*ADDITIONAL RADIATOR	Not Necessary	959.00 FS	*- FS
36	2		*RADIATOR BRACKET-UPPER	Not Necessary	90.00 FS	*- FS
37	2		*RADIATOR BUSH-LOWER	Not Necessary	22.00 FS	*- FS
38	6		*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
39	2		*RADIATOR AIR GUIDE-LH/RH	Torn	56.00 FS	*44.32 FS
40	1		*RADIATOR SEAL-OUTER RH	Not Necessary	9.00 FS	*- FS
41	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	14.00 FS	*- FS
42	2		*WINDSCREEN WATER DEFLECTOR STRIP-LH/RH	Not Necessary	150.00 FS	*- FS
43	1		*FRONT NO PLATE	Necessary	100.00 FS	*100.00 FS
44	1		*SUNDRIES	Necessary	300.00 FS	*105.60 FS
45	1		*FRONT WHEEL HOUSING LINER-LH (Supplementary)	Torn	183.00 FS	*146.40 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **27,307.00**    **18,060.72**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,CHARGE AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT,PRESSURISE COOLING SYSTEM,VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHT.TO REPAIR BOTH FENDER.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,900.00	2,250.00
5	TO RESPRAY FRONT BUMPER,BONNET HINGES,BOTH FRONT FENDER AND BOTH UPPER A-PILLAR	New	5,000.00	1,260.00
6	TO REAPPLY PAINT COATING FOR FRONT BONNET AND FRONT BUMPER (BY OWNER)	New	400.00	350.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,952.00</b>	<b>6,312.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >