



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6268P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER CLIPS	NOT NECESSARY	2.10	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY,RR BUMPER RH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY,RR BUMPER RH	NOT NECESSARY	139.60	-
1	ANTENNA,ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	BUMPER SEAL,RR LH	NOT NECESSARY	88.90	-
1	BUMPER SEAL,RR RH	NOT NECESSARY	65.70	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	TAILGATE ASY	NOT NECESSARY	1,007.90	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	NAME PLATE (PRIUS)	NOT NECESSARY	60.80	-
1	NAME PLATE (TOYOTA)	NOT NECESSARY	51.90	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 65558888	NOT NECESSARY	21.60	-
1	END PANEL	NOT NECESSARY	602.10	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			4,708.70	-
LABOUR				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER REAR.			507.00	200.00
SPRAY PAINT.			1,296.00	200.00
TO WASH AND VACUUM.			60.00	-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
			2,323.00	400.00
	GRAND TOTAL		7,031.70	400.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			300.00

Report Ref No. NS/INC22000910/Rvy3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.