

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000913/KEA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000102
Claimant Vehicle No :	SKR189P	Insured Vehicle No :	SMT2219P
Date of Loss:	22/01/2022	Nature of Claim:	TP
		Claim No:	1272688942SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR189P	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 PERFORMANCE, 2.0 E (A)	Chassis No:	LRW3F7EC8MC385543
Reg. Date:	14/12/2021 (Man. Year: 2021)	Odometer:	1094 km
Colour:	Metallic Red		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R20	Rear Tyre Size:	235/35 R20
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,408.41	160.00	1,248.41	88.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	400.00	750.00	65.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,558.41	560.00	1,998.41	78.11
+ GST 7.00/7.00% (S\$)	179.09	39.20	139.89	78.11
Nett Amount (S\$)	2,737.50	599.20	2,138.30	78.11
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		806.65		
Global Sum Settlement (S\$)		800.00		

INSPECTION

Date of Assignment:	26/01/2022		
Date Inspected:	26/01/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	1,009.35 FL	*- FL
2	1		*CERAMIC COATING	Necessary	500.00 FS	*160.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					1,509.35	160.00
- List Item Discount on L Items 10.00/10.00% (S\$)					100.94	0.00
Total Parts (S\$)					1,408.41	160.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR & READJUST ACCIDENT AREA	New	400.00	150.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	400.00	250.00
3	TO CHECK WIRING & ELECTRICAL SYSTEM	New	150.00	0.00
4	TO DIAGNOS FAULT CODE & RESET MEMORY	New	200.00	0.00
Gross Labour Cost (S\$)			1,150.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >