

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000915/UTY3N2**Date:** 14/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00036202103

Claimant Vehicle No : GBH8241C **Insured Vehicle No :** GBA1966C

Date of Loss: 31/12/2021 Nature of Claim: TP Claim No: SNM22D200037/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH8241C**

Make & Model: NISSAN NV200, 1.5 (M) Engine No: K9KE628D623076

Reg. Date: 10/10/2018 (Man. Year: 2018) Chassis No: VSKYBAM20Z0172945

Colour: Red Odometer: 0 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14 Rear Tyre Size: 175/70R14

Front Left Side: Comforser 5 mm Rear Left Side: Comforser 5 mm

Front Right Side: Comforser 5 mm Rear Right Side: Comforser 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,443.07	7,273.14	4,169.93	36.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,430.00	990.00	28.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,863.07	9,703.14	5,159.93	34.72
Approved Total (Overridden) (S\$)		7,750.00		
(S\$)	14,863.07	7,750.00	7,113.07	47.86
+ GST 7.00/7.00% (S\$)	1,040.41	542.50	497.91	47.86
Nett Amount (S\$)	15,903.48	8,292.50	7,610.98	47.86

INSPECTION

Date of Assignment: 25/01/2022

Date Inspected: 26/01/2022 Inspected At: Ethoz Group Ltd - Tampines (HQ)
22 TAMPINES STREET 92
Singapore 528876

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Mar 2022)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH8241C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	655.20 FN	*563.50 FN
2	2		*FRONT BUMPER RETAINER	Cracked	50.00 FN	*50.00 FN
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
4	1		*FRONT BUMPER SPONGE	Not fitted	275.40 FN	*- FN
5	1		*FRONT BUMPER REINFORCEMENT	Bent	766.50 FN	*614.90 FN
6	1		*FRONT BUMPER TOW COVER	Deformed	30.00 FN	*30.00 FN
7	1		*FOGLAMP RH/LH	N/s Cracked/O/s Not Necessary	642.00 FN	*321.00 FN
8	1		*FRONT GRILLE	Cracked	356.80 FN	*356.80 FN
9	1		*FRONT GRILLE LOGO	Missing	64.90 FN	*64.90 FN
10	10		*FRONT GRILLE CLIPS	Necessary	50.00 FN	*50.00 FN
11	2		*HEADLAMP RH/LH	Cracked	789.00 FN	*789.00 FN
12	1		*HEADLAMP LOWER PANEL RH/LH	N/s Bent/O/s Repair	737.00 FN	*348.60 FN
13	1		*BONNET	Bent/Buckled	864.20 FN	*864.20 FN
14	1		*BONNET LOCK	Twisted	65.00 FN	*65.00 FN
15	2		*BONNET HINGE	Bent	130.00 FN	*130.00 FN
16	1		*SUPPORT TOP PANEL	Bent	708.00 FN	*507.50 FN
17	2		*SUPPORT PANEL RH/LH	Bent / Twisted	150.00 FN	*150.00 FN
18	1		*SUPPORT LOWER PANEL	Repair	530.00 FN	*- FN
19	1		*FRONT FENDER LH	Distorted	555.20 FN	*548.20 FN
20	1		*FRONT FENDER INNERSHIELD LH	Torn	194.50 FN	*194.50 FN
21	10		*FRONT FENDER SHIELD CLIPS	Necessary	50.00 FN	*50.00 FN
22	1		*FRONT WHEELHOUSE PANEL LH	Repair	650.00 FN	*- FN
23	1		*AIRCON CONDENSER	Bent/Punctured	696.80 FN	*696.80 FN
24	1		*RADIATOR	Not Necessary	716.00 FN	*- FN
25	2		*FRONT AIRGUIDE RH/LH	Torn	100.00 FN	*100.00 FN
26	1		*RADIATOR FAN ASSY	Not Necessary	656.00 FN	*- FN
27	1		*FRONT WHEEL HUB CAP LH	Not Necessary	145.00 FN	*- FN
28	1		*FRONT DOOR LH	Bent	1,287.50 FN	*1,219.70 FN
29	1		*REAR FENDER LH (SCRATCHED)(NPA)	Not Consistent With The Impact	0.00 FN	*- FN
30	1		*TAILLAMP LH	Not Necessary	277.30 FN	*- FN
31	2		*FRONT CHASSIS PANEL RH/LH (NPA)	Repair	0.00 FN	*- FN
32	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
33	1		*COOLANT	Necessary	30.00 FS	*20.00 FS
34	1		*ROC DOOR STICKER LH	Necessary	40.00 FS	*30.00 FS
35	1		*ADVERTISEMENT STICKER FRT	Necessary	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	12,667.30	8,049.60
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,224.23	776.46
Total Parts (\$\$)	11,443.07	7,273.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,400.00	1,000.00
2	TO RESPRAY AFFECTED AREAS	New	1,400.00	1,200.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	20.00
4	TO REMOVE AND TRANSFER DOOR COMPONENTS	New	100.00	60.00
5	TO PULL AND REALIGN FRONT CHASSIS PANEL	New	300.00	0.00
6	TO TOP UP AIRCON GAS	New	120.00	100.00
7	TOWING BILL	New	50.00	50.00
Gross Labour Cost (\$\$)			3,420.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >