

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000916/KTY3N2**Date:** 25/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00007272000

Claimant Vehicle No : SMR3053D **Insured Vehicle No :** SMJ6399D

Date of Loss: 24/01/2022 Nature of Claim: TP Claim No: SNM22D200623/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR3053D**

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) Engine No: 2ZR2F32852

Reg. Date: 27/12/2019 (Man. Year: 2019) Chassis No: ZWR800413868

Colour: Metallic Black Odometer: 114661 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: TRISTAR 9 mm Rear Left Side: Roadstone 6 mm

Front Right Side: TRISTAR 9 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,961.35	6,770.02	5,191.33	43.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,860.00	1,950.00	51.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,771.35	8,630.02	7,141.33	45.28
Approved Total (Overridden) (\$\$)		6,500.00		
Nett Amount (\$\$)	15,771.35	6,500.00	9,271.35	58.79

INSPECTION

Date of Assignment: 21/02/2022

Date Inspected: 08/02/2022 Inspected At: Lian Her Motors (Ang Mo Kio)
Blk 5038, Ang Mo Kio Industrial Park 2, #01-405
Singapore 569541

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2022)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3053D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE	Bent	1,650.70 FL	*1,650.70 FL
2	1		*REAR TAIL-GATE INNER TRIM BOARD	Buckled	550.70 FL	*550.70 FL
3	1		*REAR TAIL-GATE OUTER CHROME HANDLE	Mtg Cracked	425.70 FL	*425.70 FL
4	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	185.70 FL	*185.70 FL
5	1		*REAR TAIL-GATE EMBLEM HYBRID	Necessary	65.10 FL	*65.10 FL
6	1		*REAR TAIL-GATE INNER LOCK	Dented	285.60 FL	*285.60 FL
7	1		*REAR TAIL-GATE INNER LOCK SENSOR	Dented	325.70 FL	*325.70 FL
8	1		*REAR ANTENNA SENSOR	Serviceable	225.10 FL	*- FL
9	1		*REAR TAIL-LAMP (LED)	Ns Mtg Cracked/Os Serviceable	2,026.40 FL	*781.00 FL
10	2		*REAR NO PLATE LAMP	Serviceable	130.20 FL	*- FL
11	1		*REAR FENDER INNER TRIM BOARD	N/s Cracked	1,310.20 FL	*655.10 FL
12	1		*REAR TAIL-LAMP LOWER GARNISH	N/s Dented/Buckled	711.20 FL	*355.60 FL
13	1		*REAR END PANEL	Bent	650.10 FL	*650.10 FL
14	1		*REAR END PANEL INNER GARNISH	Buckled	205.20 FL	*205.20 FL
15	1		*REAR BOOT FLOOR PANEL	Repair	955.60 FL	*- FL
16	1		*REAR BOOT FLOOR PANEL TOP COVER BOARD }	Dented	1,107.60 FL	*1,107.60 FL
17	2		*REAR BOOT FLOOR PANEL SIDE COVER BOARD }	Dented	0.00 FL	*- FL
18	1		*REAR BUMPER-COLOUR CODE	Bent	1,055.10 FL	*1,021.30 FL
19	1		*REAR N/S BUMPER REFLECTOR	Serviceable	105.10 FL	*- FL
20	1		*REAR BUMPER TOW COVER	Missing	55.70 FL	*55.70 FL
21	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	311.40 FL	*155.70 FL
22	1		*REAR SPARE TOOL COMPARTMENT COVER	Serviceable	187.60 FL	*- FL
23	1		*REAR AIR CON BLOWER	Serviceable	2,250.80 FL	*- FL
24	1		*REAR REVERSE CAMERA	Serviceable	400.00 FS	*- FS
25	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
26	20		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
27	1		*REAR REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
28	1		*REAR BOOT RUBBER (50%)	Distorted/Dented	198.98 FS	*132.65 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) 15,655.48 8,889.15
- List Item Discount on L Items 25.00/25.00% (\$) 3,694.13 2,119.13

Total Parts (\$) 11,961.35 6,770.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,500.00	600.00
2	TO PUTTY AND SPRAY PAINT	New	1,500.00	900.00
3	CHECK AND RECONNECT WIRING	New	40.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	150.00	60.00
5	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	100.00	60.00
7	REMOVE/RENEW AIR CON BLOWER & TO TOP UP GAS	New	250.00	0.00
8	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	150.00	100.00
Gross Labour Cost (\$\$)			3,810.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >